



~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
245 PEACHTREE CENTER AVENUE NE, SUITE 1200
ATLANTA, GEORGIA 30303-1257

July 13, 2012

Mr. David A. Heacock
President and Chief Nuclear Officer
Virginia Electric and Power Company
Dominion Nuclear
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

SUBJECT: SURRY POWER STATION - NRC SECURITY INSPECTION REPORT
05000280/2012403 AND 05000281/2012403

Dear Mr. Heacock:

On June 14, 2012, the U.S. Nuclear Regulatory Commission (NRC) completed a security baseline inspection at your Surry Power Station. The inspection covered one or more of the key attributes of the security cornerstone of the NRC's Reactor Oversight Process. The enclosed Inspection Report documents the inspection results, which were discussed on June 14, 2012, with Mr. L. Lane and other members of your staff.

The inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.

No NRC-identified or self-revealing findings were identified during this inspection. However, one licensee-identified violation which was determined to be of very low safety significance is listed in this report. The NRC is treating this violation as a non-cited violation (NCV) consistent with Section 2.3.2, of the NRC Enforcement Policy. If you contest any NCV violation in the enclosed report, you should provide a response within 30 days of the date of this inspection report, with the basis of your denial, to the Nuclear Regulatory Commission, Administrator, Region II; the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Resident Inspector at the Surry Power Station.

~~Enclosure(s) transmitted herewith contain(s) SUNSI. When separated from enclosure(s), this transmittal document is decontrolled.~~

~~LIMITED INTERNAL
DISTRIBUTION PERMITTED~~

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

D. Heacock

2

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's Agency wide Document and Management System (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response, if any. This practice will ensure that your response will not be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system, ADAMS. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark your entire response "Security-Related Information-Withhold Under 10 CFR 2.390" and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Sincerely,

/RA/

Binoy Desai, Chief
Plant Support Branch 2
Division of Reactor Safety

Docket No. 50-280, 50-281
License No. DPR-32, DPR-37

Enclosure:
Inspection Report 05000280/2012403 and
05000281/2012403 w/Att: Supp Info (**OUO**)

cc w/encl.: (See page 3)

~~OFFICIAL USE ONLY – SECURITY-RELATED INFORMATION~~

~~OFFICIAL USE ONLY – SECURITY RELATED INFORMATION~~

D. Heacock

2

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's Agency wide Document and Management System (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosure will not be available for public inspection.

In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response, if any. This practice will ensure that your response will not be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system, ADAMS. If Safeguards Information is necessary to provide an acceptable response, please provide the level of protection described in 10 CFR 73.21. Otherwise, mark your entire response "Security-Related Information-Withhold Under 10 CFR 2.390" and follow the instructions for withholding in 10 CFR 2.390(b)(1).

Sincerely,

/RA/

Binoy Desai, Chief
Plant Support Branch 2
Division of Reactor Safety

Docket No. 50-280, 50-281
License No. DPR-32, DPR-37

Enclosure:
Inspection Report 05000280/2012403 and
05000281/2012403 w/Att: Supp Info **(OUO)**

cc w/encl.: (See page 3)

Distribution w/encl:

- RidsNrrPMSurry Resource
- C. Evans, RII EICS (Part 72 Only)
- L. Douglas, RII EICS (Linda Douglas)
- B. Westreich, NSIR (hard copy w/ encl)
- R. Albert, NSIR RII
- S. Coker, NSIR RII
- RIDSNRRDIRS
- OE Mail (email address if applicable)
- PUBLIC (W/O OUO)**

PUBLICLY AVAILABLE NON-PUBLICLY AVAILABLE SENSITIVE NON-SENSITIVE
ADAMS: Yes ACCESSION NUMBER: ML12195A354 SUNSI REVIEW COMPLETE FORM 665 ATTACHED

OFFICE	RII:DRS/PSB2	RII:DRS/PSB2	RII: DRS/PSB2	RII: DRS/PSB2	RII: DRS/PSB2	RII: DRS/PSB2	RII: DRP/BR5B
SIGNATURE	RA/AR Via Email	RA/JS Via Email	RA/JS For KD	RA/AT Via Email	RA/RP Via Email	RA/BD	RA/GM Via Email
NAME	A. Richardson	J. Shehee	K. Davis	A. True	R. Patterson	B. Desai	G. McCoy
DATE	07/11/2012	07/10/2012	07/13/2012	07/10/2012	07/11/2012	07/12/2012	07/10/2012
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	

OFFICIAL RECORD COPY DOCUMENT NAME: G:\DRS\PSB\REACTORS\SURRY\REPORTS\2012\SURRY INSP REPORT 2012403REV2-W-OUTOUO.DOC

D. Heacock

3

cc w/Encl:

Nelson K. Martin

Manager

Nuclear Fleet Protection Services

Virginia Electric and Power Company

Innsbrook Technical Center

5000 Dominion Boulevard

Glen Allen, VA 23060-6711

Margaret A. Earle

Nuclear Licensing and Operations Support

Innsbrook Technical Center

5000 Dominion Boulevard

Glen Allen, VA 23060-6711

cc w/Inspection Summary:

Gregory S. Haynes

Manager, Nuclear Protection Services

Surry Power Station

5570 Hog Island Road

Surry, VA 23883-0315