

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Janx Integrity Group 10599 Dallas Drive Terre Haute, Indiana REPORT NUMBER(S) 12-002		2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-11772	4. LICENSE NUMBER(S) 21-16560-01	5. DATE(S) OF INSPECTION 6/13/2012	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Bill C. Lin		7/2/12
BRANCH CHIEF	Hironori Peterson	 for	7/7/12

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Janx Integrity Group 10599 Dallas Drive Terre Haute, Indiana REPORT NUMBER(S) 12-002	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-11772	4. LICENSE NUMBER(S) 21-16560-01	5. DATE(S) OF INSPECTION 6/13/2012
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87121	7. INSPECTION FOCUS AREAS FE1-FE7
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT William Reeves, RSO	4. TELEPHONE NUMBER (517) 531-8210
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: 06/2013

Field Office Inspection 10599 Dallas Drive, Terre Haute, Indiana

Temporary Job Site Inspection _____

PROGRAM SCOPE

The licensee is a radiography company with the corporate office located in Parma, Michigan. The licensee has numerous field stations within NRC and Agreement States jurisdictions. The corporate radiation safety officer (RSO) is located in the Parma, Michigan office and he reports directly to the Safety Director. Currently, the main radiographer for 10599 Dallas Drive is operating out of his residence. Records generated by the radiographers at the Terre Haute location are mailed to the licensee's corporate office each week.

Performance Observation

At the time of the inspection, the radiographers were not performing any industrial radiography within NRC jurisdictions. The NRC inspector did not have the opportunity to observe the performance of an industrial radiography operation at a temporary job site. The licensee's radiography truck was locked and secured while the vehicle was parked outside the radiographer's residence. The licensee demonstrated to the inspector the following: daily equipment checks, setting up radiation area boundaries, daily survey instruments check, dosimetry checks, radiation survey techniques, and leak test procedures. The demonstrations were performed in accordance with all applicable regulatory requirements. The radiographers were knowledgeable of all safety requirements and procedures.

The inspector was unable to review the radiation safety records at the time of the inspection. All of the radiation safety records are located at the licensee's corporate office in Parma, Michigan. However during the inspection, the inspector held a conference call with the corporate RSO and discussed information such as the radiographers' dosimetry records, radiation safety training, and field audits. All of the information provided by the licensee's RSO was in accordance with NRC regulatory requirements. The radiation safety records located at the licensee's corporate office will be reviewed during an NRC inspection at that facility.

No violations of NRC requirements were identified.