

35

Erickson, Alice

From: Morey, Dennis *max*
Sent: Friday, December 02, 2011 9:16 AM
To: Lehman, Bryce; Sheikh, Abdul; Erickson, Alice
Cc: CuadradoDeJesus, Samuel; Sakai, Stacie; Ferrer, Nathaniel
Subject: RE: Davis-Besse Shield Building

Bryce,

The issue with the D-B crack is that the location and direction of the crack are not clear from the diagrams.

Next, I think we should say that operability is still being discussed. If D-B is allowed to start up, there needs to be a slide describing why it is OK.

Finally, I think the LR impact needs to be clearer (on the final slide):

- Degraded concrete is a Part 50 issue affecting license renewal
- DLR needs to understand if the degradation is age-related and progressive etc. and how the effect will be managed
- DLR has prepared a draft RAI asking the applicant to explain how the unique OE will be addressed by its AMPs
 - Currently holding the RAI until more information is known in the Part 50 arena (root cause, proposed solution, etc.)
 - This will be tracked as an Open Item in SER

Thanks,

Dennis Morey

From: Lehman, Bryce *max*
Sent: Thursday, December 01, 2011 4:45 PM
To: Sheikh, Abdul; Erickson, Alice
Cc: CuadradoDeJesus, Samuel; Sakai, Stacie; Morey, Dennis
Subject: Davis-Besse Shield Building

Attached are the most recent slides for our brief with Melanie on Davis-Besse (3:15 on Tuesday). If you have time please review and provide feedback.

Alice, I made some minor changes and added a slide to the presentation you originally sent. Thanks for your help!

Abdul, The information in the presentation was accurate as of 11/18, but we could really use your help updating it to reflect what has happened since then. We especially need help filling in slide 10 'NRC's Concerns.' If you don't think you will be able to get to this by Monday afternoon, please let me know so Alice and I can plan accordingly.

Thanks,

Bryce Lehman

O-11F10

(301) 415-1626

Bryce.Lehman@nrc.gov

B
35