

Comanche Peak Nuclear Power Plant, Units 3 & 4
 COL Application
 Part 2, FSAR

5Hz+10Hz, 10^{-4}

- ϵ : 2+
- ϵ : 1 to 2
- ϵ : 0 to 1
- ϵ : -1 to 0
- ϵ : -2 to -1




Figure 2.5.2-223 Deaggregation of 10^{-4} Rock Hazard for 5 and 10 Hz