

030-13133



> PerkinElmer
2200 Warrenville Road
Downers Grove, IL 60515
Phone: 630-969-6000
Fax: 630-969-6193
www.perkinelmer.com

Date: 8/9/2012

To: U.S. NRC
Licensing Branch
Division of Materials Safety and State Agreements
Washington, DC 20555-0001
Attn: Richard K. Struckmeyer

Subj: Letter of Notification – re: Lic. No. 12-04933-06E, Exempt Radioactive
Material Supplier Change

To whom it may concern,

This is to inform the NRC that PerkinElmer's previous supplier of exempt level
tube type calibration sources has been changed.

FROM

Canberra Industries, Inc.
107 Union Valley Road
Oak Ridge, TN 37830
(865) 220-6333
www.canberra.com
Contact Person: Carmen Jones

TO

Spectrum Techniques, LLC
106 Union Valley Road
Oak Ridge, TN 37830
(865) 482-9937
www.spectrumtechniques.com
Contact Person: Larry Webb

As with Canberra in the past, the PerkinElmer Downers Grove Illinois site will
now only be ordering from Spectrum, or have drop-shipped to various US and
international customers, and in some cases receiving and re-shipping the
following isotopes in various piece-part quantities.

578064

PE EXEMPT PICO-CALIBRATOR MASTER LIST			
ISOTOPE	TOTAL ACTIVITY PER P/N (uCi)	PERKINELMER DESCRIPTION	PE PART NUMBER
I-125	0.120	I125 PICO-Calibrator (Set/1)	5080125
	0.240	I125 PICO-Calibrator (Set/2)	5080225
	0.360	I125 PICO-Calibrator (Set/3)	5080325
	0.600	I125 PICO-Calibrator (Set/5)	5080525
	1.200	I125 PICO-Calibrator (Set/10)	5081025
	1.440	I125 PICO-Calibrator (Set/12)	5081225
	1.800	I125 PICO-Calibrator (Set/15)	5081525
	1.920	I125 PICO-Calibrator (Set/16)	5081625
	2.400	I125 PICO-Calibrator (Set/20)	5082025
	3.000	I125 PICO-Calibrator (Set/25)	5082525
I129	0.060	I129 PICO-Calibrator (Set/1)	5080129
	0.120	I129 PICO-Calibrator (Set/2)	5080229
	0.180	I129 PICO-Calibrator (Set/3)	5080329
	0.240	I129 PICO-Calibrator (Set/4)	5080429
	0.300	I129 PICO-Calibrator (Set/5)	5080529
	0.360	I129 PICO-Calibrator (Set/6)	5080629
	0.600	I129 PICO-Calibrator (Set/10)	5081029
	0.720	I129 PICO-Calibrator (Set/12)	5081229
	0.900	I129 PICO-Calibrator (Set/15)	5081529
	0.960	I129 PICO-Calibrator (Set/16)	5081629
	1.200	I129 PICO-Calibrator (Set/20)	5082029
	1.440	I129 PICO-Calibrator (Set/24)	5082429
	1.500	I129 PICO-Calibrator (Set/25)	5082529
	0.050	I-129 Calibration Source	6018504

Cr51	3.600	Cr51 PICO-Calibrator (Set/1)	5080151
	7.200	Cr51 PICO-Calibrator (Set/2)	5080251
	10.800	Cr51 PICO-Calibrator (Set/3)	5080351
	14.400	Cr51 PICO-Calibrator (Set/4)	5080451
	18.000	Cr51 PICO-Calibrator (Set/5)	5080551
	21.600	Cr51 PICO-Calibrator (Set/6)	5080651
	36.000	Cr51 PICO-Calibrator (Set/10)	5081051
	43.200	Cr51 PICO-Calibrator (Set/12)	5081251
	54.000	Cr51 PICO-Calibrator (Set/15)	5081551
	57.600	Cr51 PICO-Calibrator (Set/16)	5081651
	72.000	Cr51 PICO-Calibrator (Set/20)	5082051
	86.400	Cr51 PICO-Calibrator (Set/24)	5082451
	90.000	Cr51 PICO-Calibrator (Set/25)	5082551
	Co57	0.120	Co57 PICO-Calibrator (Set/1)
0.240		Co57 PICO-Calibrator (Set/2)	5080257
0.360		Co57 PICO-Calibrator (Set/3)	5080357
0.600		Co57 PICO-Calibrator (Set/5)	5080557
1.200		Co57 PICO-Calibrator (Set/10)	5081057
1.440		Co57 PICO-Calibrator (Set/12)	5081257
1.800		Co57 PICO-Calibrator (Set/15)	5081557
1.920		Co57 PICO-Calibrator (Set/16)	5081657
2.400		Co57 PICO-Calibrator (Set/20)	5082057
Cs137	0.25	Cs-137 Calibration Source	6018503

PerkinElmer is nearing the end of its transition from Canberra to Spectrum, and expects to be completed by or before 8/31/2012.

If you have any question, feel free to contact me at (630) 322-5202.

Best regards,

A handwritten signature in cursive script that reads "R. Haines".

Rick Haines
QA/RA Mgr, RSO/LSO
PerkinElmer