

NRC FORM 591M PART 1 (07-2012) 10 CFR 2.201 **U.S. NUCLEAR REGULATORY COMMISSION**
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Downriver Cardiology Consultants, P.C. 23050 West Street, Suite 120 Brownstown, Michigan 48183 REPORT NUMBER(S) 12-01	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	--

3. DOCKET NUMBER(S) 030-32396	4. LICENSE NUMBER(S) 21-26330-01	5. DATE(S) OF INSPECTION 8/21/12
---	--	--

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.




3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
 (Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE	KEVIN J. BERLIN, D.O.		9-10-12
NRC INSPECTOR	Michael G. Herr, CHP		8-29-12
BRANCH CHIEF	Tamara E. Bloomer		9/5/12

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Downriver Cardiology Consultants, P.C. 23050 West Street, Suite 120 Brownstown, Michigan 48183 REPORT NUMBER(S) 12-01	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-32396	4. LICENSE NUMBER(S) 21-26330-01	5. DATE(S) OF INSPECTION 8/21/12
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS 03.01-03.08
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Kevin J Berlin, D.O/RSO	4. TELEPHONE NUMBER (734) 675-5720
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: August 2017

Field Office Inspection

Temporary Job Site Inspection

PROGRAM SCOPE

This licensee was a small cardiology clinic authorized to use licensed material under 10 CFR 35.200. The nuclear medicine department was staffed with two part time technologists who performed approximately 50+ diagnostic procedures a week. License activities are currently conducted on Monday through Thursday but the next inspector should verify hours of operation prior to inspection as the days of operation tend to change. The license only receives unit doses for cardiac studies. The licensee was in the process of moving to their new location to Brownstown, Michigan. The inspectors initially arrived at the Brownstown location, no license activities have been conducted at this site at the time of inspection.

The inspection included observing security of material, instrument use, area posting, and hot lab operations. The licensee also demonstrated dose calibrator QA checks, package receipts and surveys. Various records were also reviewed including dosimetry records, waste disposal records, survey records, annual audits, and instrument check records.

No violations were identified at this time.