

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Dr. Anil K. Goel 1915 E. 14 Mile Road Birmingham, Michigan 48009</p> <p>REPORT NUMBER(S) 2012-001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>	
<p>3. DOCKET NUMBER(S)</p> <p>030-37802</p>	<p>4. LICENSE NUMBER(S)</p> <p>21-32683-01</p>	<p>5. DATE(S) OF INSPECTION</p> <p>Sept. 10, 2012</p>

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Geoffrey Warren		9/10/12
BRANCH CHIEF	Tamara Bloomer		9/20/12

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Dr. Anil K. Goel 1915 E. 14 Mile Road Birmingham, Michigan 48009 REPORT NUMBER(S) 2012-001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-37802	4. LICENSE NUMBER(S) 21-32683-01	5. DATE(S) OF INSPECTION September 10, 2012
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS 03.01 - 03.07
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02220	2. PRIORITY 3	3. LICENSEE CONTACT Dr. Anil Goel, M.D.	4. TELEPHONE NUMBER (248) 723-4777
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: Sept. 2015

Field Office Inspection

Temporary Job Site Inspection

PROGRAM SCOPE

The licensee was a cardiology clinic located in Birmingham, Michigan, with authorization to use byproduct materials in Sections 35.100 and 35.200. Licensed activities were conducted only at the location indicated on the license. While authorized to perform work at temporary job sites, the licensee had never done so and had no plans to begin in the near future. Licensed activities were conducted one day each week, alternating Mondays and Wednesdays. The nuclear medicine department was staffed with one contract nuclear medicine technologist who also performed work for other licensees. The technologist typically administered 10 cardiac doses daily. The clinic received unit doses as needed from a licensed nuclear pharmacy. All waste was either held for decay-in-storage (DIS) or returned to the nuclear pharmacy.

Performance Observations

The inspector observed two diagnostic administrations of licensed material, including dose preparation and disposal. The technologist demonstrated survey meter and wipe counter QC, package receipt and return surveys and wipes, dose calibrator constancy, and daily contamination surveys and wipes, and described spill procedures and other activities. The inspector noted no concerns with these activities. Interviews with licensee personnel indicated adequate knowledge of radiation safety concepts and procedures. Review of dosimetry records indicated no doses of regulatory concern. The inspector performed independent and confirmatory radiation measurements which indicated results consistent with licensee survey records and postings.