

### AR 01319937 Report

<b>Aff Fac:</b>	Byron	<b>AR Type:</b>	CR	<b>Status:</b>	APPROVED
<b>Aff Unit:</b>	02	<b>Owed To:</b>	A8810CAP	<b>Due Date:</b>	02/29/2012
<b>Aff System:</b>	VP			<b>Event Date:</b>	01/30/2012
<b>CR Level/Class:</b>	4/D			<b>Disc Date:</b>	01/30/2012
<b>How Discovered:</b>	H01			<b>Orig Date:</b>	01/30/2012
<b>WR/PIMS AR:</b>		<b>Equip Tag:</b>	2VP03CB - 2B PRI CNMT VENT CRDM EXH FAN MOTOR		

### Action Request Details

**Subject:** 2VP03CB DID NOT START

**Description:** Originator: (b)(6) Supv Contacted: (b)(6)

Condition Description:  
During SAT failure, 2VP03CB did not start.

Immediate actions taken:  
None specified

Recommended Actions:  
None Specified

List of knowledgeable individuals:

(b)(6)

Operable Basis:

Reportable Basis:

Functionality Basis:

SOC Reviewed by: (b)(6) 01/30/2012 16:28:00 CST  
SOC Comments:  
Close to WR. ZINWR 1/30/12

### Assignments

<b>Assign #:</b>	01	<b>Assigned To:</b>		<b>Status:</b>	AWAIT/C
------------------	----	---------------------	--	----------------	---------

Information in this record was deleted in accordance with the Freedom of Information Act.  
Exemptions 6  
FOIA/PA 2012-0287

<b>Aff Fac:</b>	Byron	<b>Prim Grp:</b>	ACAPALL	<b>Due Date:</b>	02/04/2012
<b>Assign Type:</b>	TRKG	<b>Sec Grp:</b>		<b>Orig Due Date:</b>	
<b>Priority:</b>					
<b>Schedule Ref:</b>					
<b>Unit Condition:</b>					
<b>Subject/Description:</b>	2VP03CB DID NOT START				