

AR 01320205 Report

Aff Fac:	Byron	AR Type:	CR	Status:	APPROVED
Aff Unit:	02	Owed To:	ACAPALL	Due Date:	02/29/2012
Aff System:	SY			Event Date:	01/30/2012
CR Level/Class:	/			Disc Date:	01/30/2012
How Discovered:	H02			Orig Date:	01/30/2012
WR/PIMS AR:		Equip Tag:	-		

Action Request Details

Subject: U-2 345 KV OUTPUT BREAKER GCB 10-11 FAILED TO CLOSE

Description: Originator: (b)(6) Supv Contacted: (b)(6)

Condition Description:
 U-2 345 kv OUTPUT BREAKER GCB 10-11 failed to close. Two attempts per BOP SY-12 attempted, phase to phase voltages matched. The other U-2 345 kv OUTPUT BREAKER OCB 11-12 did close, the first breaker requested by switching order # 699980.

Immediate actions taken:
 Informed Unit Supervisor

Recommended Actions:
 Reverse closure sequence or use keyed syncho-check option.

Operable Basis:

Reportable Basis:

Functionality Basis:

Assignments

Assign #:	01	Assigned To:		Status:	AWAIT/C
Aff Fac:	Byron	Prim Grp:	ACAPALL	Due Date:	02/04/2012
Assign Type:	TRKG	Sec Grp:		Orig Due	

Date:

Priority:

Schedule Ref:

Unit Condition:

Subject/Description: U-2 345 KV OUTPUT BREAKER GCB 10-11 FAILED TO CLOSE