NRC FORM 591M PART 1 U.S. NUCLEAR REGULATORY COMMISSION (07-2012) 10 CFR 2,201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
1. LICENSEE/LOCATION INSPECTED: Heart Cardiology Consultant, P.C. 22250 Providence Drive Suite 705 Southfield, MI 48075			2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352				
REPORT NUMBER(S	s) 2012-001		,				
3. DOCKET NUMBER(S)		4. LICENSE NUMBE	R(S)	5. DATE(S) OF INSPECTIO	V		
030-35565		21-32278-01		09/12/2012			
Regulatory Commiss procedures and representation of the procedure of the p	in examination of the activities conduction (NRC) rules and regulations and the sentative records, interviews with persentative records, interviews with persentative records, interviews with persentative records, interviews with persentative records, no violations with violation(s) closed. Itions(s), specifically described to you be ditive, and corrective action was or is being were satisfied. Non-cited violation(s) were discussed.	e conditions of your connel, and observa were identified. The inspector as no sing taken, and the	license. The inspection consistentions by the inspector. The inspector on-cited violations, are not being remaining criteria in the NRC Enf	ed of selective examination of the control of the c	ns of ws: self-identified,		
cited in ac with 10 C	is inspection, certain of your activities, a ecordance with NRC Enforcement Polic FR 19.11. is and Corrective Actions)	as described below cy. This form is a No	and/or attached, were in violation	n of NRC requirements an ay be subject to posting in	d are being accordance		
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.							
TITLE	PRINTED NAME		SIGNATURE		DATE		
LICENSEE'S REPRESENTATIVE							
NRC INSPECTOR	Bill C. Lin		BM	>	10/5/12		
BRANCH CHIEF	T. Bloomer		HE Down		0/9/1		

NRC FORM 591M PART 3 U.S. NUCLEAR REGULATORY COMMISSION (07-2012) Docket File Information								
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION								
1. LICENSEE/LOCATION INSPECT	ED:		2. NRC/REGIONAL OFFICE					
Heart Cardiology Consult 22250 Providence Drive Suite 705 Southfield, MI 48075 REPORT NUMBER(S) 2012-			Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352					
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S	6)	5. DATE(S) OF INSPECTION				
030-35565		21-32278-01		09/12/2012				
6. INSPECTION PROCEDURES USED 87130		7. INSPECTION FOCUS 3.01-3.07	7. INSPECTION FOCUS AREAS 3.01-3.07					
SUPPLEMENTAL INSPECTION INFORMATION								
1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTAC Souhei Saba, M.		4. TELEPHONE NUMBER (248) 552-9858				
✓ Main Office Inspection Next Inspection Date: 09/2017 ☐ Field Office Inspection ☐ Temporary Job Site Inspection								
PROGRAM SCOPE								
This was a routine inspection of a licensee in Southfield, Michigan. The licensee is a small cardiology clinic that is staffed with one nuclear medicine technologist (NMT). The NMT performs approximately nine procedures per day using unit doses. The clinic receives its unit doses from the local nuclear pharmacy.								
Performance Observations								
The inspection consisted of tour of the facility and independent measurements. The inspector interviewed the radiation safety officer (RSO), and closed the previous violation from the routine safety inspection performed in 2008. At the time of the inspection, the NMT had left for vacation. However, the inspector was able to interview the NMT the following week. The NMT appeared knowledgeable regarding radiation safety, and waste handling techniques. The inspector also performed an in office review of additional inspection documents such as training records, instrument calibration records, and dosimetry records. The inspector performed an telephone exit with the licensee on October 3, 2012.								
No violations of NRC requirements were identified for this inspection.								
,								