

U.S. NUCLEAR REGULATORY COMMISSION

TELEPHONE CONVERSATION RECORD

Date: 10/18/12

Time: 9:00 AM

Mail Control 579100 License No(s). 47-30941-01 Docket No(s). 030-36640
or Report No(s).

Name of Licensee: Mobile Diagnostics, LLC (MD)

Name of Participant(s): Curtis Nichols, CNMT/Owner
Janice Nguyen

Telephone No. 304-522-7000

Subject: Inquiry about license termination

(NOTE: This will be used as the
Documents Title in ADAMS)

The licensee submitted a request for license termination, including a NRC Form 314. MD is a mobile operation and they submitted close-out surveys for their vans. All unsealed material was returned to the radiopharmacy and waste was appropriately decayed and surveyed prior to disposal. I just wanted to clarify the statement in the letter that said that they didn't possess any sealed sources. MD and Pro Imaging Diagnostics, LLC (NRC License Number 47-25522-01) are owned by the same person and share the same address and hot lab. MD did not possess any sealed sources per Mr. Nichols. Camera QC was done at client sites using a Tc-99m point source in a unit dosage. They did not use a dose calibrator at the client site (dosages were assayed by performing decay calculations). The well counter that was used was the one in the Pro Imaging hot lab (which had a Pro Imaging rod source). Since all sealed sources that were possibly used by MD were actually owned and inventoried by Pro Imaging, I do not require a final sealed source inventory for MD. Also, since Pro Imaging is still in operation, I do not require a close-out survey of the hot lab.

Action Required: Process license termination.

Document Availability:

☒

Publicly Available

☐

Non-Publicly Available

☒
☐
☐

Non-Sensitive

Sensitive – Privacy Act (includes PII)

Immediate Release

☐
☐

Non-Sensitive Copyright

Sensitive – Internal

Normal Release Date: 10/26/2012

☐
☐

Sensitive- Proprietary

Sensitive – Security-Related

Delayed Release Date:

SUNSI Review Completed By: Janice Nguyen / RA /

Document Accession #: _____