NRC FORM 591M PART 1 (10-2011)* 10 CFR 2:201 SAFETY INSPECTION REPORT AND COMPL			U.S. NUCLEAR REGULATORY COMMISSION	
	TECTION REPORT		<u> </u>	
1. LICENSEE/LOCATION INSPECTED: Robert M. Smith, M.D. 310 Collins Street Hartford, CT 06105		2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
REPORT NUMBER(S) 2012-001			<u> </u>	
3. DOCKET NUMBER(S)	4. UCENSE NUMBER	• -	5. DATE(S) OF INS	
030-34922	06-	30496-01	Septerr	nber 24, 2012 to 10 10/12
LICENSEE: The inspection was an examination of the activi Regulatory Commission (NRC) rules and regula procedures and representative records, interviee  1, Based on the inspection findings, in	ations and the conditions of ws with personnel, and ob	of your license. The servetions by the	he inspection consisted of selection	ve examinations of
2. Previous violation(s) closed.				
3. The violation(s), specifically described to you by the inspector as non-clied violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.				
Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):				
4. During this inspection, certain of your extivities, as described below and/or attached, were in violation of NRC requirements and are being ched in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)  10 CFR 35.14(b)(5) requires, in part, that the licensee shall notify the Commission no later than 30 days after the licensee has added to or changed the areas of use identified in the application or on the license where byproduct material is used in accordance with either 10 CFR 35.100 or 35.200. Contrary to the above, Robert M. Smith, M.D., did not notify NRC within 30 days after adding an area of use identified on the license. Specifically, between November 2010 and September 26, 2012, a lock box used to store radioactive material packages delivered by the radiopharmacy before normal business hours, was added to an area of their facility, and the NRC was not notified. Robert M. Smith, M.D., sent a notification on September 26, 2012, to amend their license to include this location as part of their facilities.				
Statement of Corrective Actions				
I hereby state that, within 30 days, the sotions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.				
Title	Printed Name	40	Signature	Date
LICENSEE'S REPRESENTATIVE RO	BERTMSM	MH.	Kourt Muit	1, MO 20/10/12
NRC INSPECTOR	Maryann Abogunde	•	Alexand	10/[0/12
BRANCH CHIEF			Janes P. Dunge	10/11/12
*NRC FORM 591M PART 1 (10-2011) (RI Rev. 08/04/2012) G:\WordDocs\Cuirrent\Insp Record\R06-30496-01.2012001.591M-Part1.doc				
SUNSI Review Completed By: /RA			X Public	X Non-Sensitive