

**CAMECO RESOURCES
CROW BUTTE OPERATION**



**86 Crow Butte Road
P.O. Box 169
Crawford, Nebraska 69339-0169**

**(308) 665-2215
(308) 665-2341 – FAX**

October 8, 2012

**CERTIFIED MAIL
RETURN RECEIPT REQUESTED**

Mr. Michael Linder, Director
Nebraska Department of Environmental Quality
P.O. Box 98922
Lincoln, NE 68509-8922

Subject: Class III UIC Permit NE0122611
September 2012 Monthly Restoration Report

Dear Mr. Linder:

Please find enclosed the September 2012 Monthly Restoration Reports for Mine Units 2, 3, 4, 5 and 6. The reverse osmosis (RO) units continue to inject permeate and reductant into Mine Units 2, 3, 4, and 5. IX treatment continued in Mine Unit 6.

If you have any questions regarding this submittal, please feel free to contact me at (308) 665-2215, ext. 114.

Sincerely,
Cameco Resources
Crow Butte Operation

A handwritten signature in black ink that reads "Larry Teahon". The signature is written in a cursive, flowing style.

Larry Teahon
SHEQ Manager

Enclosures: As Stated

cc: Lindsey Phillips, NDEQ Chadron Office
Ron Burrows, NRC
CBO File
ec: CR - Cheyenne

CROW BUTTE MINE
 MONTHLY RESTORATION REPORT
 SEPTEMBER 2012
 MINE UNIT 2

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep		X	(if yes, complete part 3)
c. Groundwater Treatment	X		RO and Reductant PR15, P97, P113, I180P, I188P, and P209.
d. Wellfield Recirculation		X	
e. Other (explain):		X	

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

P97, P113, I180P, I188P, and P209.

CROW BUTTE MINE
 MONTHLY RESTORATION REPORT
 SEPTEMBER 2012
 MINE UNIT 3

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep		X	(if yes, complete part 3)
c. Groundwater Treatment	X		RO and Reductant CM1-11, IJ13P, I298P, and RES3E.
d. Wellfield Recirculation		X	
e. Other (explain):		X	

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

CM1-11, I298P, and RES3E.

CROW BUTTE MINE
 MONTHLY RESTORATION REPORT
 SEPTEMBER 2012
 MINE UNIT 4

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep		X	(if yes, complete part 3)
c. Groundwater Treatment	X		RO and Reductant P371, P372, P430, P434, and P437.
d. Wellfield Recirculation		X	
e. Other (explain):			

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

CM2-4, P371, P372, P430, P434, and P437.

CROW BUTTE MINE
 MONTHLY RESTORATION REPORT
 SEPTEMBER 2012
 MINE UNIT 5

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep		X	(if yes, complete part 3)
c. Groundwater Treatment	X		RO and Reductant I676P, P707, P773, P800, I854P, and P922.
d. Wellfield Recirculation		X	
e. Other (explain):		X	

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

I676P, P707, P773, P800, and I854P.

CROW BUTTE MINE
 MONTHLY RESTORATION REPORT
 SEPTEMBER 2012
 MINE UNIT 6

1. RESTORATION ACTIVITY DURING MONTH:

	YES	NO	
a. Groundwater Transfer		X	(if yes, complete part 2)
b. Groundwater Sweep		X	(if yes, complete part 3)
c. Groundwater Treatment	X		IX P1268, P1283, P1312, P1314, P1348, P1370, P1494, P1497, P1531, P1559, P1573, P1588, P1596, P1612, P1633, P1703, P1715, P1751, P1756, P1778, P1800, and P1857.
d. Wellfield Recirculation		X	
e. Other (explain):		X	

2. LIST WELLS USED IN GROUNDWATER TRANSFER DURING THE MONTH:

3. LIST WELLS USED IN GROUNDWATER SWEEP DURING THE MONTH:

4. LIST WELLS SAMPLED DURING MONTH AND ASSAY RESULTS:

P1268, P1283, P1312, P1314, P1370, P1494, P1497, P1531, P1573, P1588, P1596, P1612, P1633, P1703, P1715, P1751, P1756, P1778, P1800, and P1857.



7010 0780 0000 1422 2943



**RETURN RECEIPT
REQUESTED**



CAMECO RESOURCES
Crow Butte Operation
86 Crow Butte Road
P.O. Box 169
Crawford, NE
69339 USA

Mr. Ron Burrows, Project Manager
Decommissioning and Uranium Recovery Licensing
Directorate
Division of Waste Management and Environmental
Protection
Office of Federal and State Materials and
Environmental Management Programs
Mailstop T8-F5
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001