

(10-2011)*
10 CFR 2.201

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Department of the Army, U.S. Army Research, Development and Engineering Command 5183 Blackhawk Road, Aberdeen Proving Grounds, Maryland REPORT NUMBER(S) 2012-001 and 2012-002		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER(S) 030-04552	4. LICENSE NUMBER(S) 19-10306-01	5. DATE(S) OF INSPECTION 11/13 + 14/2012	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

- ☒ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

10CFR20.1801 requires that the licensee secure from unauthorized removal and access licensed material that are stored in controlled or unrestricted areas. Contrary to the above, on November 13, 2012, the licensee did not secure from unauthorized removal or limit access to 70 millicuries of Ni-63 foils located in Building 3160, which is a Controlled Area. The area was secured. Radiation Safety Officer will ensure retaining of the Authorized user of the lab and formal implementation of lab safety audit containing a security check. Complete by 12/13/2012.

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	PAUL MADAIR	Paul Mair	11/14/12
NRC INSPECTOR	Dennis Lawyer	Dennis Lawyer	11/14/12
BRANCH CHIEF	Judith Joustra	Judith A. Joustra	11/24/12

SUNSI Review Completed By: / RA / Dennis Lawyer

☒ Public☒ Non-Sensitive