United States Nuclear Regulatory Commission Official Hearing Exhibit

In the Matter of:

Entergy Nuclear Operations, Inc. (Indian Point Nuclear Generating Units 2 and 3)

ASL Doc Exh Adm

ASLBP #: 07-858-03-LR-BD01 **Docket #**: 05000247 | 05000286 **Exhibit #**: ENT000047-00-BD01

Admitted: 10/15/2012

Rejected: Other: Identified: 10/15/2012

Withdrawn: Stricken:

Stephen B. Bram Vice President



ENT000047 Submitted: March 28, 2012

Consolidated Edison Company of New York, Inc. Indian Point Station Broadway & Bleakley Avenue Buchanan, NY 10511 Telephone (914) 737-8116

January 17, 1990

Re: Indian Point Unit No. 2 Docket No. 50-247

Document Control Desk US Nuclear Regulatory Commission Mail Station P1-137 Washington, DC 20555

SUBJECT: Response to Request for Additional Information Regarding Response to Generic Letter 89-08, 'Erosion/Corrosion-Induced Pipe Wall

Thinning' (TAC No. 73496)

The subject generic letter requested us to provide information on the implementation of a long-term erosion/corrosion monitoring program for high-energy carbon steel systems at Indian Point Unit No. 2. We provided our response by letter dated July 20, 1989, which stated that our program meets the intent of the NUMARC guidelines described in Appendix A of NUREG-1344. A November 30, 1989 letter from D.S. Brinkman to S.B. Bram requested us to confirm that our program actually meets the NUMARC guidelines or to identify any exceptions to those guidelines and to describe how our program is equivalent.

The program described in our previous response is consolidated into a document entitled "Inspection Program to Monitor Erosion/Corrosion in Piping Systems at Indian Point Unit No. 2". A copy of this document is available for review at the station. We believe that the program described in this document does meet the NUMARC guidelines described in Appendix A of NUREG-1344.

Should you or your staff have any questions regarding this matter, please contact Mr. Charles W. Jackson, Manager, Nuclear Safety and Licensing.

Very truly yours,

cc: Mr. William Russell
Regional Administrator - Region I
US Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Donald S. Brinkman, Senior Project Manager Project Directorate I-1 Division of Reactor Projects I/II US Nuclear Regulatory Commission Mail Stop 14B-2 Washington, DC 20555

Senior Resident Inspector
US Nuclear Regulatory Commission
PO Box 38
Buchanan, NY 10511
9001310254 900117
PDR ADOCK 05000247

A001

PROP



NOTICE

THE ATTACHED DOCUMENT MAY CONTAIN "PROPRIETARY INFORMATION" AND SHOULD BE HANDLED AS NRC "OFFICIAL USE ONLY" INFORMATION. IT SHOULD NOT BE DISCUSSED OR MADE AVAILABLE TO ANY PERSON NOT REQUIRING SUCH INFORMATION IN THE CONDUCT OF OFFICIAL BUSINESS AND SHOULD BE STORED, TRANSFERRED, AND DISPOSED OF BY EACH RECIPIENT IN A MANNER WHICH WILL ASSURE THAT ITS CONTENTS ARE NOT MADE AVAILABLE TO UNAUTHORIZED PERSONS.

	COPY NO
	DOCKET NO
**	CONTROL NO
	REPORT NO
*	REC'D W/LTR DTD.

PROPRIETARY INFORMATION