



DEC 03 2012

L-2012-435
10 CFR 50.55a

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555-00001

Re: Turkey Point Unit 3
Docket No. 50-250
Inservice Inspection Program
Fourth Interval-Third Period-First Refueling Outage
Owner's Activity Report (OAR-1)

Attached find the Owner's Activity Report (Form OAR-1), for Turkey Point Unit 3 Fourth Inservice Inspection Interval, Third Period, First Refueling Outage (PTN 3-26). The Form OAR-1, Owner's Activity Report, implements Code Case N-532-4.

Should there be any questions concerning this report, please contact Robert J. Tomonto at 305-246-7327.

Very truly yours,

A handwritten signature in black ink, appearing to read 'Michael Kiley', with a stylized flourish at the end.

Michael Kiley
Vice President
Turkey Point Nuclear Plant

SM

Attachment

A047
NRR

L-2012-435, Attachment

FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number: ISI-PTN-3-2012

Plant: Turkey Point Nuclear Power Plant Unit 3
9760 SW 344th Street
Homestead, Florida 33035

Commercial Service Date: December 14, 1972 Refueling Outage No.: PTN 3-26

Current Inspection Interval: ISI-Fourth IWE-Second IWL Second

Current Inspection Period: ISI-Third IWE-Second IWL - 40th Year

Edition and Addenda of Section XI applicable to the inspection plans: ISI-1998 Edition with Addenda through 2000 and IWE & IWL -2001 with Addenda through 2003.

Date and Revision of inspection plans: ISI-July 23, 2010 Rev. 3 IWE-March 3, 2009, Rev.0
IWL - November 2010 Rev. 0

Edition and Addenda of Section XI applicable to repairs and replacements, if different than the inspection plan: Same

Code Cases Used: N-460, N-532-4, N-533-1, N-566-1, N-616, N-623, N-624, N-658, N-686, N-722-1

CERTIFICATE OF CONFORMANCE

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the inspection plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of PTN 3-26 conform to the requirements of Section XI.

Signed Robert A. Colarte CONFORMANCE SIGNATURE & INSPECTIONS MGR Date 11/30/12
RD GIL Owner or Owner's Designee, Title

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of Florida and employed by HSBCT of Hartford Connecticut have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Robert A. Colarte Commissions FL 11-000684 (A,C,N,I)
Inspector's Signature National Board, State, Province, and Endorsements

Date 11-30-12

L-2012-435, Attachment
FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 1 ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED EVALUATION FOR CONTINUED SERVICE		
Examination Category and Item Number	Item Description	Evaluation Description
B-B/B2.11	Pressurizer Circumferential Weld	Evaluate for slag inclusions in weld. Acceptable for continued service
D-A/D1.20	Welded Attachment	Evaluate for missed final NDE during installation of new support. Acceptable for continued service until next cycle.

L-2012-435, Attachment
FORM OAR-1 OWNER'S ACTIVITY REPORT

TABLE 2 ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE				
Code Class	Item Description	Description Of Work	Date Completed	Repair/Replacement Plan Number
1	Reactor Head Nuts	Replace	8/12/12	RR40034260-01
1	Heat Exchanger	Repair gouges in channel head	8/12/12	RR39010145-05
1	Piping and fittings	Cut out for license renewal commitment for testing	8/12/12	RR40152465-01
2	Piping and Elbow	Replace due to low wall readings from internal corrosion	6/22/12	RR40047871-01
3	Spring Can Support	Swap spring cans to proper configuration	11/15/12	RR40068968-95
3	Condensate Storage +Tank Vent Piping	Replace vent piping on tank	3/11/12	RR40011000-03