

Appendix

NOTICE OF VIOLATION

Radiation Management Corporation

Docket No. 40-08801

As a result of the inspection conducted on May 17, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

10 CFR 71.5 prohibits delivery of licensed materials to a carrier for transport unless the licensee complies with applicable regulations of the Department of Transportation in 49 CFR Parts 170-189.

49 CFR 173.392(c)(1) requires that shipments of Low Specific Activity (LSA) materials must be packaged in strong, tight packages.


Contrary to the above, one package (Drum No. 205) in your shipment No. 1175-004 was shipped from your facility on May 13, 1983, and arrived at the Richland, Washington burial site on May 17, 1983, with an open lid. Therefore, the drum did not meet the requirement for a strong, tight package.

This is a Severity Level III violation (Supplement V).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

JUL 27 1983

Dated

  
J. R. Miller, Chief  
Materials and Safeguards Branch

9710210041

9710210041 971015 Corp  
PDR FOIA  
VOOCT97-272 PDR

B/28