

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Shalom Services Corp
737 Southshire Dr.
ST. LOUIS, MO 63125

2. NRC/REGIONAL OFFICE
Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

REPORT NUMBER(S) ~~2012-001~~ *13-01*

3. DOCKET NUMBER(S)
030-37474

4. LICENSE NUMBER(S)
24-32655-01

5. DATE(S) OF INSPECTION
2/6/13

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the Inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	E.L. Kulzer	<i>E.L. Kulzer</i>	<i>2/6/13</i>
BRANCH CHIEF	<i>T.E. Bloomer</i>	<i>Ben Cantel for</i>	<i>2/15/13</i>

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Shalom Services 737 Southshire Drive St. Louis, MO 63125 REPORT NUMBER(S) 13-01	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-37474	4. LICENSE NUMBER(S) 24-32655-01	5. DATE(S) OF INSPECTION 2/6/2013
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED IP 87124	7. INSPECTION FOCUS AREAS 03.01 through 03.07
---	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3121	2. PRIORITY 5	3. LICENSEE CONTACT Funmi Ojo	4. TELEPHONE NUMBER (314) 894-1066
--------------------------------	----------------------	--------------------------------------	---

Main Office Inspection Next Inspection Date: 2/6/2018

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

The inspector went to the address on record as having the gauge and determined that the company was no longer at that location. The inspector then went to the mailing address on the license which was the home of the owner. Mr. Ojo stated that he has stored the gauge at R.M. Wester and Mr. Ojo provided a notice to NRC dated 5/3/2012 stating as much. The inspector reviewed the license for R.M. Wester (NRC License No. 24-32655-01) and determined that R. M. Wester was authorized to store the Humboldt gauge at their facility in St. Peters, MO.

The inspector reviewed the required records for the gauge for 2010-2012 which included inventory, leak test, and dosimetry records. No violations of NRC requirements were identified.

The inspector has put the letter of 5/30/2012 from Shalom Services to NRC in ADAMS for future inspections.