



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
1600 EAST LAMAR BLVD
ARLINGTON, TEXAS 76011-4511

FEBRUARY 22, 2013

MEMORANDUM TO: Robert Sun, Health Physicist (T-8E24)
Radioactive Materials Safety Branch
Division of Materials Safety & State Agreements

FROM: G. Michael Vasquez, Chief */RA ADGaines/ for*
Nuclear Materials Safety Branch A
Division of Nuclear Materials Safety

SUBJECT: MATERIALS LICENSEE EVENT REPORT SUMMARY

Enclosed is the subject report for February, 2013. This enclosure documents the licensee event reports that were closed in December 2012 and January 2013 and lists ADAMS ML numbers for documents associated with these events, detailing Region IV's response.

Enclosure:
February 2013 RIV DNMS Licensee
Event Reports Summary Table

cc via email w/Enclosure

- E. Collins
- A. Vogel
- V. Campbell
- J. Whitten
- D. Spitzberg
- J. Thompson
- D. Huntsman [Dante.Huntsman@inl.gov]

Hard Coy
 LER File

S:\DNMS\INMIB\LERs\2012\12-2012 & 1- 2013.doc

| | | | | | |
|---------------------------------------|--|--|---|---|------------------------|
| ADAMS | | <input type="checkbox"/> No | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> SUNSI Review Complete | Reviewer Initials: JLT |
| | | <input checked="" type="checkbox"/> Publicly Available | | <input checked="" type="checkbox"/> Non-sensitive | |
| | | <input type="checkbox"/> Non-publicly Available | | <input type="checkbox"/> Sensitive | |
| KEYWORD: SUNSI Review Complete | | | | | |
| RIV:DNMS/NMSB-A | | | C:NMSB-A | | |
| JLThompson | | | GMVasquez | | |
| /RA/ | | | /RA ADGaines/ for | | |
| | | | | | |

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - FEBRUARY 2013

| ADAMS ML # or Event # | Event Date | Notification Date | Licensee | License Number | Reporting Requirement | Event Description | Assigned Inspector | Review Status |
|--------------------------|---------------|----------------------|------------------------------|-------------------|--------------------------|---|-----------------------|------------------|
| 47309 | 9/30/2011 | 10/3/2011 | United States Air Force | 42-23539-01AF | 10 CFR 20.2201 | Lost americium-241 sealed source (12 millicurie) | Cook | Open |
| 48193 | 8/15/2012 | 8/15/2012 | United States Air Force | 42-23539-01AF | 10 CFR 20.2201 | Lost americium-241 sealed source (0.25 millicuries) in a CAD | Cook | Open |
| 47996 | 6/5/2012 | 6/5/2012 | Inberg-Miller Engineers | 49-19477-01 | 10 CFR 30.50 | Troxler portable nuclear gauge was damaged at a temporary jobsite when run over in Cheyenne, Wyoming | Munoz | Open |
| 48532 | 11/22/2012 | 11/23/2012 | Bayou Inspection Services | LA-7112-L01 | 10 CFR 30.50 | Radiography source disconnect on pipe lay barge in offshore Federal waters near Louisiana | Stearns | Open |
| 48516 | 11/16/2012 | 11/17/2012 | Acuren USA | 42-32443-01 | 10 CFR 30.50 | Radiography source disconnect on the north slope of Alaska | Razo | Open |
| ML13015A182 | 12/9/2012 | 1/3/2013 | Schlumberger | 42-00090-03 | 10 CFR 39.77 | Well logging source abandonment, cesium-137 and Am-241 source | Thompson | Closed |
| ML13036A574 | 1/11/2013 | 2/5/2013 | Schlumberger | 42-00090-03 | 10 CFR 39.77 | Well logging source abandonment, cesium-137 and Am-241 source | Poston | Closed |
| ML13036A552 | 12/25/2012 | 1/16/2013 | Schlumberger | 42-00090-03 | 10 CFR 39.77 | Well logging source abandonment, cesium-137 density source | Poston | Closed |