

February 20, 2013

MEMORANDUM TO: SSD Case File **#13-03**
Siemens Medical Systems, Inc.

Sealed Source and Device Registration(s)
NR-8272-D-801-E (Supersedes NR-0602-D-101-S)

FROM: Lymari Sepulveda **/RA/**
Licensing Branch, FSME/MSSA

SUBJECT: No Checklist or Safety Evaluation Performed

On October 5, 2012, the Licensing Branch received an e-mail from Rosalyn Jones/Accounts Receivable Branch indicating that the registration certificate NR-0602-D-101-S was still active; however, the materials licenses associated with it were terminated. License No. 29-10598-01 was terminated on May 5, 1995, when the licensee moved from RI to RIV. Region IV issued a new license No. 04-30203-01. The license No. 04-30203-01 is shown in the WBL as retired and the last action type associated to it was a termination. The Licensing Branch reviewed the information and determined that an inactive registration certificate should be issued.

Based on the information above the registration certificate NR-0602-D-101-S has been inactivated. For the inactivation, no checklist was used because no safety evaluation was performed.