

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 02/28/2013)**

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME5167	RIS 'Staff Position on the Clarification of Submitting of Alter. Under 10 CFR 50.55'	O	26.0	12/13/2010	DCI
ME7896	RIS 'Content Specification and Shielding Evaluations for Type B Packages'	O	13.0	01/27/2012	NMSS
ME8702	RIS 'Applicability of GDC Requirements for External Events in Operability Determinations'	O	9.0	05/17/2012	DSS
ME8865	RIS 'Changes to NOED Process and Staff Guidance'	O	8.0	06/12/2012	DPR
ME9020	RIS 'Embedded Digital Devices in Safety Systems'	O	7.0	07/09/2012	NRO
ME9732	RIS 'Resolution of Top Nozzles Stress Corrosion Cracking Issues'	O	4.0	10/04/2012	NMSS
MF0415	RIS 'Use of Aftermarket Sealed Sources Registered Under 10 CFR 32.210'	O	2.0	12/21/2012	FSME
MF0416	RIS 'NRC Staff Position on Use of ASME Certification Mark'	O	2.0	12/21/2012	DE
MF0467	RIS 'Maintaining Effective Aging Management Programs'	O	1.0	01/07/2013	DLR
MF0685	RIS 'Impact of Sequestration on NRC Activities and NRC Stakeholders'	O	1.0	02/21/2013	DPR
MF0541	RIS 'NRC Position on SSCs Requiring Protection from Tornado Missiles'	O	1.0	01/23/2013	DSS
ME9179	IN 'Counterfeit Fire Protection Equipment'	O	6.0	08/06/2012	DE
ME9615	IN 'Recent Issue With The Definition Of Core Quadrant'	O	5.0	09/25/2012	DSS
ME9779	IN 'Concrete Subsurface Laminar Cracking'	O	4.0	10/15/2012	RIII

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 02/28/2013)**

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME9789	IN 'Design Vulnerabilities in Dry Pipe and Pre-Action Fire Water Systems'	O	4.0	10/15/2012	DRA
MF0327	IN 'Cracking Issues Related to Steam Dryer Component in BWR Units with Power Uprates'	O	2.0	12/06/2012	DE
MF0492	IN 'Battery Aging Margin and Its Potential Impact on Surveillance Requirements'	O	1.0	01/12/2013	DE
MF0580	IN 'Radioactive Effluent Radiation Monitoring Systems'	O	1.0	01/29/2013	DPR
MF0652	IN 'Flammable Gases'	O	1.0	02/12/2013	PGCB
MF0670	IN 'Fuel Safety Limit Calculation Inputs Were Inconsistent with NRC-Approved Fuel Design'	O	1.0	02/14/2013	DSS
ME9142	GL 'Post-Fire Safe-Shutdown Circuit Analysis Spurious Actuations'	O	7.0	07/26/2012	DRA
ME9843	GL 'Treatment of Natural Phenomena Hazards At Fuel Cycle Facilities'	O	4.0	10/25/2012	NMSS
MF0581	GL 'Degradation of Neutron Absorbing Material in Spent Fuel Pools'	O	1.0	01/29/2013	DSS