



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**
REGION III
2443 WARRENVILLE ROAD, SUITE 210
LISLE, IL 60532-4352

March 29, 2013

Mr. Larry Weber
Senior Vice President and
Chief Nuclear Officer
Indiana Michigan Power Company
Nuclear Generation Group
One Cook Place
Bridgman, MI 49106

SUBJECT: DONALD C. COOK NUCLEAR POWER PLANT, UNITS 1 AND 2
TEMPORARY INSTRUCTION 2515/186, "INSPECTION OF PROCEDURES
AND PROCESS FOR RESPONDING TO POTENTIAL AIRCRAFT THREATS";
INSPECTION REPORT NO. 05000315/2013406; 05000316/2013406

Dear Mr. Weber:

On February 28, 2013, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at your Donald C. Cook Nuclear Power Plant using Temporary Instruction 2515/186, "Inspection of Procedures and Processes for Responding to Potential Aircraft Threats." The enclosed inspection report documents the results of the inspection, which were preliminarily discussed with you and other members of your staff.

The objective of this inspection was to assess the implementation procedures and processes of your Donald C. Cook Nuclear Power Plant that are required by Title 10 of the Code of Federal Regulations (CFR) 50.54(hh)(1), which provides the requirements for responding to a potential aircraft threat. The results from this inspection, along with the results from this inspection performed at other operating commercial nuclear plants in the United States, will be used to evaluate the U.S. nuclear industry's readiness to safely respond to similar events. These results will also help the NRC to determine if additional regulatory actions are warranted.

The inspection examined activities conducted under your license as they relate to the implementation of 10 CFR 50.54(hh)(1), your compliance with the Commission's rules and regulations, and with the conditions of your operating licenses. Within these areas, the inspection involved examination of selected procedures and representative records, observations of activities, and interviews with personnel.

Based on results of this inspection, no NRC-identified or self-revealed findings were identified. However, three security-related observations were identified by the inspectors which required additional clarification and attention by the licensee. The observations were of very low safety significance and were determined not to be violations of regulatory requirements.

Enclosure transmitted herewith contains
Sensitive Unclassified Non-Safeguards
Information. When separated from enclosure,
this transmittal document is decontrolled.

L. Weber

-2-

If you contest any finding or the subject in this report, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington DC 20555-0001, with copies to the Regional Administrator, Region III; the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Resident Inspector at Donald C. Cook Nuclear Power Plant.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records System (PARS) component of NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, the material enclosed herewith contains Security-Related Information in accordance with 10 CFR 2.390(d)(1) and its disclosure to unauthorized individuals could present a security vulnerability. Therefore, the material in the enclosure will not be made available electronically for public inspection in the NRC Public Document Room or from the PARS component of NRC's ADAMS. If you choose to provide a response and Security-Related Information is necessary to provide an acceptable response, please mark your entire response "Security-Related Information – Withhold from public disclosure under 10 CFR 2.390" in accordance with 10 CFR 2.390(d)(1) and follow the instructions for withholding in 10 CFR 2.390 (b)(1). In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response.

Should you have any questions regarding this inspection, we will be pleased to discuss the issues with you.

Sincerely,

/RA/

Hironori Peterson, Chief
Operations Branch
Division of Reactor Safety

Docket Nos. 50-315; 50-316
License Nos. DPR-58; DPR-74

Nonpublic Enclosure: Inspection Report 05000315/2013406; 05000316/2013406
w/Attachment: Supplemental Information

cc w/encl:	S. Coker, NSIR/DSO/DDSO/ST	B. Desai, RII
	R. Albert, NSIR	D. Funk, RIII
	B. Huffman, NSIR/DPR/DDIR/OB	M. Haire, RIV
	J. Kozal, NSIR/DPR/DDIR/CB	K. Yale, State Liaison Officer, State of
	E. Bowman, NRR/DPR/PGCB	Michigan
	T. Dimitriadis, RI	
cc w/o encl:	Distribution via ListServ™	

~~OFFICIAL USE ONLY - SECURITY-RELATED INFORMATION~~

L. Weber

-2-

If you contest any finding or the subject in this report, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington DC 20555-0001, with copies to the Regional Administrator, Region III; the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Resident Inspector at Donald C. Cook Nuclear Power Plant.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records System (PARS) component of NRC's Agencywide Documents Access and Management System (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, the material enclosed herewith contains Security-Related Information in accordance with 10 CFR 2.390(d)(1) and its disclosure to unauthorized individuals could present a security vulnerability. Therefore, the material in the enclosure will not be made available electronically for public inspection in the NRC Public Document Room or from the PARS component of NRC's ADAMS. If you choose to provide a response and Security-Related Information is necessary to provide an acceptable response, please mark your entire response "Security-Related Information – Withhold from public disclosure under 10 CFR 2.390" in accordance with 10 CFR 2.390(d)(1) and follow the instructions for withholding in 10 CFR 2.390 (b)(1). In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response.

Should you have any questions regarding this inspection, we will be pleased to discuss the issues with you.

Sincerely,
/RA/
Hironori Peterson, Chief
Operations Branch
Division of Reactor Safety

Docket Nos. 50-315; 50-316

License Nos. DPR-58; DPR-74

Nonpublic Enclosure: Inspection Report 05000315/2013406; 05000316/2013406
w/Attachment: Supplemental Information

cc w/encl: S. Coker, NSIR/DSO/DDSO/ST
R. Albert, NSIR
B. Huffman, NSIR/DPR/DDIR/OB
J. Kozal, NSIR/DPR/DDIR/CB
E. Bowman, NRR/DPR/PGCB
T. Dimitriadis, RI
B. Desai, RII
D. Funk, RIII
M. Haire, RIV
K. Yale, State Liaison Officer, State of Michigan

cc w/o encl: Distribution via ListServ™

DISTRIBUTION w/o encl:

See next page

DOCUMENT NAME: DCC 2013 406 OUO Cover Letter.docx

☒ Publicly Available ☐ Non-Publicly Available ☐ Sensitive ☒ Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII	RIII	RIII	I
NAME	RKWalton:cs	JMaynen	HPeterson	
DATE	03/28/13	03/29/13	03/29/13	

OFFICIAL RECORD COPY

~~OFFICIAL USE ONLY - SECURITY-RELATED INFORMATION~~

Letter to Mr. Larry Weber from Mr. Hironori Peterson dated March 29, 2013.

SUBJECT: DONALD C. COOK NUCLEAR POWER PLANT, UNITS 1 AND 2
TEMPORARY INSTRUCTION 2515/186, "INSPECTION OF PROCEDURES
AND PROCESS FOR RESPONDING TO POTENTIAL AIRCRAFT THREATS";
INSPECTION REPORT NO. 05000315/2013406; 05000316/2013406

DISTRIBUTION w/o encl:

Doug Huyck
RidsNrrDorLpl3-1 Resource
RidsNrrPMDCCook Resource
RidsNrrDirslrib Resource
Chuck Casto
Cynthia Pederson
Steven Orth
Allan Barker
Christine Lipa
Carole Ariano
Linda Linn
DRPIII
DRSIII
Patricia Buckley
Tammy Tomczak
ROPreports.Resource@nrc.gov