

RECEIVED
MAY 28 2013

DNMS

May 24, 2013

NRC – Region IV
Nuclear Materials Safety Branch B
612 East Lamar Blvd.; Suite 400
Arlington, TX 76011-4125

**RE: Revision to Facilities Authorized for Radioactive Material Possession and Use
USNRC Radioactive Materials License No. 42-01068-07
Halliburton Energy Services, Inc. (Docket No. 030-06392)**

Halliburton Energy Services, Inc. requests the following amendment to the above referenced license.

Amendment – Revise License Condition 10 to **remove** the following branch office.

**Sperry Sun Drilling Services
Baroid Mud Plant
Prudhoe Bay, Alaska**
(License condition 10.A)

All radioactive materials previously in storage at this facility have been physically accounted for and transferred to Halliburton's new branch office located at 2805 Spine Road, Deadhorse, Alaska 99734. (Please reference our letter dated April 24, 2013, requesting the addition of this new branch office to our license.)


The leak test history for sealed sources previously in storage at this location confirms that there were no reported instances of detectable removable contamination above the specified regulatory limits. No unsealed or loose forms of radioactive materials were ever possessed or stored at this location under the authorizations of this license.

Radiological surveys were performed following the relocation of the radioactive material to confirm that no removable contamination or residual radioactivity existed above the regulatory-prescribed release limits.

Halliburton is retaining ownership of the Baroid Mud Plant location however it will no longer be used for the storage or use of radioactive materials authorized by this license.

Thank you for your consideration and action. Should any additional information be required, I can best be reached by e-mail at Elizabeth.Foltz@Halliburton.com or by phone at (281) 871-4255.

Sincerely,



Elizabeth A. Foltz
Global Radiation Safety Officer
Halliburton Energy Services, Inc.
Houston, Texas 77032

PUBLIC

- Immediate Release
 Normal Release

NON-PUBLIC

- A.3 Sensitive-Security Related
 A.7 Sensitive Internal
 Other: _____

Reviewer: me

Date: 06/19/13

Ref: HL1485

No. 581077

HALLIBURTON

GLOBAL RADIATION SAFETY 1002540031
3000 N. SAM HOUSTON PARKWAY, EAST • BUILDING
HOUSTON, TEXAS 77032-3219

CERTIFIED MAIL™



7007 1490 0003 3644 6815




U.S. POSTAGE PITNEY BOWES



ZIP 77032 \$ 006.11⁰
02 1W
0001378292 MAY 28 2013

NRC - REGION IV
NUCLEAR MATERIALS SAFETY BRANCH B
612 EAST LAMAR BLVD
SUITE 400
ARLINGTON, TX 76011-4125

76011412500





DATE
06/17/2013

NAME AND ADDRESS OF APPLICANT AND/OR LICENSEE Halliburton Energy Services, Inc. ATTN: Elizabeth A. Foltz Radiation Safety Officer 3000 N. Sam Houston Parkway, East Building M, Room M1F21 Houston, Texas 77032-3219	LICENSE NUMBER 42-01068-07
	MAIL CONTROL NUMBER 581077
	LICENSING AND/OR TECHNICAL REVIEWER ch

This is to acknowledge the receipt of your:

LETTER and/or APPLICATION DATED: 05/24/2013

The initial processing, which included an administrative review, has been performed.

AMENDMENT TERMINATION NEW LICENSE RENEWAL

- There were no administrative omissions identified during our initial review.
- This is to acknowledge receipt of your application for renewal of the material(s) license identified above. Your application is deemed timely filed, and accordingly, the license will not expire until final action has been taken by this office.
- Your application for a new NRC license did not include your taxpayer identification number. Please fill out NRC Form 531, located at the following link:

<http://www.nrc.gov/reading-rm/doc-collections/forms/nrc531.pdf>

Send the completed NRC Form 531, by facsimile, to the following number: (301) 415-5387

A copy of your action has been emailed to our License Fee and Accounts Receivable Branch, in our Headquarters office in Rockville, MD. You will be contacted separately if there is a fee issue involved.

Your application has been assigned the above listed **MAIL CONTROL NUMBER**. When calling to inquire about this action, please refer to this control number. Your application has been forwarded to a technical reviewer. Please note that the technical review, which is normally completed within 180 days for a renewal application (90 days for all other requests), may identify additional omissions or require additional information. If you have any questions concerning the processing of your application, our contact information is listed below:

Region IV
U. S. Nuclear Regulatory Commission
DNMS/NMSB - B
1600 E. Lamar Boulevard
Arlington, TX 76011-4511
(817) 200-1103 or (817) 200-1140

6/17/13

BETWEEN:

Accounts Receivable/Payable
and
Regional Licensing Branches

[FOR ARPB USE]
INFORMATION FROM WBL

Program Code: 03111
Status Code: Pending Amendment
Fee Category: 5A
Exp. Date:
Fee Comments:
Decom Fin Assur Reqd: Y

License Fee Worksheet - License Fee Transmittal

A. REGION

1. APPLICATION ATTACHED

Applicant/Licensee: HALLIBURTON ENERGY SERVICES, INC.
Received Date: 05/28/2013
Docket Number: 3006392
Mail Control Number: 581077
License Number: 42-01068-07
Action Type: Amendment

2. FEE ATTACHED

Amount: _____

Check No.: _____

3. COMMENTS

Signed: _____

Carol L. Hise

Date: _____

6/17/13

B. LICENSE FEE MANAGEMENT BRANCH (Check when milestone 03 is entered / /)

1. Fee Category and Amount: _____

2. Correct Fee Paid. Application may be processed for:

Amendment: _____

Renewal: _____

License: _____

3. OTHER _____

Signed: _____

Date: _____