

**From:** [BOA - Hannig, Markus](#)  
**To:** [Arribas-Colon, Maria](#)  
**Cc:** [Jankovich, John](#); [Sepulveda, Lymari](#); [Schlemm, Hans](#); [Blecher, Frank](#)  
**Subject:** RE: Request for Additional Information - In response to your letter dated May 10, 2013  
**Date:** Friday, July 05, 2013 11:48:40 AM  
**Attachments:** [Name\\_plate\\_15\\_0516\\_02.doc](#)

---

Hello Maria,

Here is my second attempt answering your question.

- 1) The correct postal address is: 425 Main Road, Towaco, NJ 07082, the physical location of our office has not changed
- 2) Postfach 1225, Am Weidekamp 10  
D-57258 Freudenberg, Germany
- 3) Also the licensing purpose, overall design, and the integrity of both Model MK 1.0 and Model MK 2.0 will not be affected by this name change.
- 4) It is just a name change.
- 5) Please find attached the label with the US distributor name and address for both MK 1.0 and MK 2.0 models. The other two labels with information on the sealed source and service interval remain the same.

I again apologize for the confusion caused by submitting the wrong labels.

Please don't hesitate contacting me for any further question.

Kindest Regards,

Markus Hannig

---

**From:** Arribas-Colon, Maria [mailto:Maria.Arribas-Colon@nrc.gov]  
**Sent:** Tuesday, June 25, 2013 9:09 AM  
**To:** BOA - Hannig, Markus  
**Cc:** Jankovich, John; Sepulveda, Lymari  
**Subject:** Request for Additional Information - In response to your letter dated May 10, 2013

Mr. Hanning,

As you requested, we are currently amending your Registration Certificates No.: NR-0122-D-101-B and NR-0122-D-102-S to reflect the Manufacturer's name change. We noted that there are discrepancies in the Registration Certificates regarding the exact addresses for both the Manufacturer and Distributor. Please see the discrepancies and additional questions for additional information listed below:

- 1) Please clarify the exact Distributor address to be used in the Registration Certificate.
  - o Registration Certificate NR-0122-D-101-B indicates that the Distributor address is the following:

*P.O. Box 18  
425 Route 202*

*Towaco, NJ 07802*

- Registration Certificate NR-0122-D-102-S indicates that the Distributor address is the following:

*425 Main Road,  
Towaco, NJ 07802*

- 2) Please clarify the exact Manufacturer address to be used in the Registration Certificate.
  - Registration Certificate NR-0122-D-101-B indicates that the Manufacturer address is the following:

*P.O. Box 1225, Am Weidekamp 10  
D-5905 Freudenberg, Germany*

- Registration Certificate NR-0122-D-102-S indicates that the Manufacturer address is the following:

*meß-und regeltechnik  
Postfach 1225, Am Weidekamp 10  
D-57258 Freudenberg, Germany*

- 3) In letter dated May 10, 2013 you stated that the name change will have no effect on the licensing, overall design, and the integrity of the Model MK 1.0 (new and old version). Please **confirm** that the licensing purpose, overall design, and the integrity of both Model MK 1.0 and Model MK 2.0 will not be affected by this name change.
- 4) Please clarify if this change is as a result of a change of control/ownership or just a name change. If this change is as a result of a change of control/ownership, please provide the information listed in Section 13.6 of Volume 3 of the NUREG 1556 series.
- 5) Provide a copy of the label with the US Distributor name and address for both MK 1.0 and MK 2.0 Models.

Please submit the requested information within 30 days of the date of this email. If we have not received complete information within 30 days of the date of this email, we will consider your application as having been abandoned by you. This is without prejudice to the submission of a complete application.

*Thank you,*

*María del Mar Arribas-Colón, M.S.*

Project Manager  
U.S. Nuclear Regulatory Commission  
FSME/MSSA/LB  
Phone: (301) 415-6026  
Email: [María.Arribas-Colon@nrc.gov](mailto:María.Arribas-Colon@nrc.gov)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---