

Copy Order #10675  
 Alyssa Rabulinski  
 Guntly & McCarthy  
 312-541-0022

[Alyssa.Rabulinski@guntlymccarthy.com](mailto:Alyssa.Rabulinski@guntlymccarthy.com)

Document Title	Accession Number	Document Date	Estimated Page Count	Microform Addresses
Notice of violation from insp on 790501-0601.	7908010227	6/13/1979	1	00400:053-00400:053
Notice of violation from insp on 790326-28.	7908020555	5/9/1979	1	00435:015-00435:015
Notice of deviation from insp on 790326-28.	7908020566	5/9/1979	1	00435:016-00435:016
Forwards revised list of welds to be inspected prior to chemical cleaning of primary sys.Replaces info in 790205 ltr,due to inaccessibility & radiation exposure problems.	7908240447	8/16/1979	2	00782:186-00782:187
Notice of violation from insp on 790801-31.	7910230247	9/13/1979	1	01196:061-01196:061
Notice of violation from insp on 790828-31.	7910240074	9/20/1979	1	01202:246-01202:246
Notice of violation from insp on 790904-28.	7912050020	10/15/1979	2	01501:021-01501:022
Notice of violation from insp on 791001-1102.	8001150403	11/16/1979	1	01749:173-01749:173
Submits supplementary info to util 740204 rept re primary coolant valve min wall thickness tabulation.Lists valves to be inspected & reviewed after primary sys decontamination.	8009300750	2/19/1974	2	03605:061-03605:062
Notice of violation from insp on 791203-800104.	8002290031	1/25/1980	1	04107:050-04107:050

Notice of violation from insp on 791009 & 1128.	8004070162	1/31/1980	1	04524:347-04524:347
Notice of violation from insp on 800220-22 & 26.	8004300548	3/11/1980	1	04722:059-04722:059
Notice of violation from insp on 800303-0404.	8006170312	4/22/1980	1	05358:029-05358:029
Notice of violation from insp on 800303-05,07,13-14,0408 & 09.	8006230020	5/6/1980	1	05413:348-05413:348
Notice of violation from insp on 800407-0502.	8007070074	5/23/1980	2	05666:296-05666:297
Notice of violation from insp on 800505-29.	8007230379	6/19/1980	1	05957:184-05957:184
Notice of violation from insp on 800428.	8008120327	5/30/1980	3	06307:241-06307:243
Notice of violation from insp on 800707-0801.	8009260399	8/18/1980	1	06615:342-06615:342
Notice of violation from insp on 780606-08,15,16,20,21 & 27-29.	8009260697	7/11/1978	1	06917:279-06917:279
Notice of violation from insp on 730808,09,16,17 & 21.	8009260702	9/13/1973	2	06917:292-06917:293
Notice of violation from insp on 770908,09,12-16 & 21.	8009250541	10/3/1977	1	06927:280-06927:280
Notice of violation from insp on 730925-27.	8009250557	11/16/1973	3	06927:336-06927:338
Insp Repts 50-010/73-04,50-237/73-04,50-249/73-05, 50-295/73-36 & 50-304/73-18 on 730925-27.Noncompliance noted:procedure prepared for insp did not include requirements for assignments of qualified inspectors. Describes valve wall thickness verification program & provides status of valve insp.Formalized program to be submitted by end of Mar 1973.Refs AEC 720629 & 0913 ltrs & util 721222 & 0814 ltrs.	8009250558	11/16/1973	16	06927:339-06927:354
	8010140653	2/15/1973	2	06927:356-06927:357

Notice of violation from insp on 770628-28 & 0708.	8009120717	8/2/1977	1	06932:006-06932:006
Notice of violation from insp on 770920-22.	8009120722	9/29/1977	1	06932:017-06932:017
AO 50-10/1975-1:on 750213,during insp of storage tank T-105A,water noted leaking from drain valve 363M6.Caused by sub-freezing temp allowing ice to form inside of valve, expanding & cracking valve.Valve replaced.	8009150578	2/20/1975	3	06932:311-06932:313
Notice of violation from insp on 770811,12,15,16 & 23-26.	8008270821	9/1/1977	1	06935:152-06935:152
Notice of violation from insp on 770824-26,30 & 31.	8008270824	9/14/1977	1	06935:160-06935:160
Notice of violation from insp on 780124-27,0202 & 23-24.	8009040655	3/22/1978	1	06937:094-06937:094
Notice of violation from insp on 771019-21 & 25.	8009040672	11/9/1977	2	06937:157-06937:158
Notice of violation from insp on 770503-05 & 10-12.	8009040679	5/23/1977	1	06937:183-06937:183
Notice of violation from insp on 780427-28 & 0502-05.	8009040686	6/28/1978	1	06937:196-06937:196
Notice of violation from insp on 780405,06,18,19 & 24-26.	8009040694	5/23/1978	1	06937:207-06937:207
Notice of violation from insp on 780302,03,07,08,14-16,22 23,27 & 28.	8009040700	4/11/1978	1	06937:224-06937:224
Notice of deviation from insp on 780302,03,07,08,14-16,22, 23,27 & 28.	8009040701	4/11/1978	1	06937:225-06937:225
Notice of violation from insp on 780202,03,07,08,14,15 & 22-24.	8009040706	3/8/1978	1	06937:251-06937:251

IE Insp Repts 50-010/76-23 & 50-249/76-25 on 761109,10,16 & 18.No noncompliance noted.Mojor areas inspected:activities associated w/refueling,startup testing of plant offgas sys & ECCS surveillance.	8009030746	11/30/1976	5 06937:314-06937:318
Notice of violation from insp on 770420-22,25,27-29,0506 & 13.	8009030822	5/26/1977	1 06938:090-06938:090
Notice of violation from insp on 800803-0906.	8011190518	9/29/1980	1 06998:122-06998:122
Responds to Sept 1980 allegations re release of contaminated water into environ.Investigation noted no detectable threat to public & insp revealed no discrepancies which could result in leakage.Forwards detailed summary of results.	8012040333	10/30/1980	11 07162:337-07162:347
Notice of violation from insp on 800907-1003.	8012100591	10/31/1980	1 07218:166-07218:166
Discusses IE insp on 800723 & forwards notice of violation & notice of proposed imposition of civil penalty.	8012300118	12/19/1980	4 07356:253-07356:256
Notice of violation from insp on 801103-07.	8101070118	11/24/1980	1 07415:013-07415:013
Notice of violation from insp on 801115-1231.	8103130233	2/3/1981	1 07912:195-07912:195
Notice of violation from insp on 810101-30. Submits response to Generic Ltr 81-03 re implementation of NUREG-0313,Revision 1 re pressure boundary piping.Increased insp & leakage detection requirements are not warranted. Inservice insp program adequately ensures safe operation.	8105050814	3/24/1981	1 08465:003-08465:003
	8107140437	7/7/1981	3 09013:222-09013:224

Notice of violation from insp on 810404-0508. Notice of violation from insp on 810706-09 & 13.	8107140757 8108050189	7/1/1981 7/24/1981	2 09017:168-09017:169 1 09257:110-09257:110
Notice of violation from insp on 810606-0702.	8108170389	7/30/1981	1 09391:143-09391:143
Notice of violation from insp on 810801-0904.	8110290434	10/15/1981	1 10387:135-10387:135
Notice of violation from insp on 810905-1002. Forwards notice of violation of insp on Dec 1977 & Jan 1978, & notice of proposed imposition of civil penalties.	8112080253 8009150619	11/24/1981 3/21/1978	2 11099:349-11099:350 11 11519:331-11519:341
Notice of violation from insp on 770524 & 26.	8009030817	6/3/1977	1 11522:287-11522:287
Notice of violation from insp on 770614-17.	8009030810	6/29/1977	1 11522:294-11522:294
Notice of deviation from insp on 771107-11. Notice of violation from insp on 771110,11,15- 18 & 22-23.	8009030771 8009030760	12/13/1977 12/6/1977	1 11522:346-11522:346 2 11523:003-11523:004
Notice of violation from insp on 771018,20,21 & 26-28.	8009040688	11/9/1977	1 11523:309-11523:309
Notice of deviation from insp on 771018,20,21 & 26-28. Responds to 720629 request for valve wall thickness verification. Asserts that program should apply only to cast valves & that 2% accuracy requirement w/ultrasonic insp methods unrealistic. Discusses specific facilities.	8009040690 8009100858	11/9/1977 8/14/1972	1 11523:310-11523:310 2 11547:111-11547:112

IE Insp Repts 50-010/81-19,50-237/81-36 & 50-249/81-28 on 811107-1204.No noncompliance noted.Major areas inspected: action on previous insp findings,operational safety verification,monthly maint observation & plant trips.	8201210221	1/8/1982	11 11648:199-11648:209
Notice of violation from insp on 811205-30.	8202160477	1/28/1982	1 11937:081-11937:081
Notice of violation from insp on 811231-820129.	8203250565	3/9/1982	2 12410:103-12410:104
Notice of violation from insp on 820130-0402.	8206070785	5/21/1982	2 13389:201-13389:202
Notice of violation from insp on 820507-0604.	8208050398	7/19/1982	2 14209:193-14209:194
Ack receipt of 781218 ltr informing NRC of steps taken to correct violations noted during insp on 781010-13 & 16-19.	7902210115	1/26/1979	1 15023:154-15023:154
Notice of deviation from insp on 781201-29.	7903190010	2/7/1979	1 15027:062-15027:062
LER 78-031/03L-0:on 781007,insp of turbine pipeway located two leaks in E extraction bypass line (2705-4"-F8).Caused by pipe erosion.One hole repaired w/welded patch & other w/ clamp-on patch.Line scheduled to be replaced during outage.	7811090124	10/27/1978	1 15030:103-15030:103
Notice of Violation from insp on 781115-17,21 & 22.	7901250325	12/29/1978	1 15030:331-15030:331
Notice of violation from insp on 780816-17.	7811010016	9/21/1978	1 15034:067-15034:067
Notice of violation from insp on 820708-0809.	8210150530	9/28/1982	1 15713:101-15713:101

Notice of violation from insp on 820810-0903.	8211060056	10/22/1982	1	15951:018-15951:018
Notice of violation from insp on 830104-0202.	8303170375	3/4/1983	1	17610:059-17610:059
Notice of violation from insp on 830315-0520.	8308030155	7/5/1983	2	19882:050-19882:051
Notice of violation from insp on 830521-0719.	8309070292	8/23/1983	2	20273:014-20273:015
Notice of violation from insp on 830829-31,0901,02 & 08.	8310210061	10/7/1983	2	20855:288-20855:289
Revised notice of violation from insp on 830720-0919.	8311290023	11/22/1983	1	21306:216-21306:216
Notice of violation from insp on 830521-0719.	8311290026	10/13/1983	2	21306:219-21306:220
Notice of violation from insp on 831118-840119.	8402170085	2/1/1984	2	22300:016-22300:017
Press release re 750128 discovery of water leaking from five small cracks in pair of 10-inch diameter stainless steel pipes causing NRC to shutdown 23 reactors of similar design on 750129 for insp.	8306150280	2/15/1975	3	23049:181-23049:183
Notice of violation from insp on 811102-06.Info deleted.	8404230044	12/22/1981	1	24184:140-24184:140
Notice of violation from insp on 821115-19.	8404230051	12/20/1982	1	24184:163-24184:163
Notice of violation from insp on 840120-0326.	8404260132	4/11/1984	2	24205:224-24205:225
Notice of violation from insp on 840415-23.	8406070061	5/24/1984	1	24747:147-24747:147
Revised notice of violation from insp on 840522-0615.	8407240557	7/8/1984	1	25731:074-25731:074
Notice of violation from insp on 840618-0726.	8408300099	8/8/1984	1	26307:203-26307:203

Notice of violation from insp on 840524-25,0716-23,0806 & 23.	8410110274	9/20/1984	3	26931:321-26931:323
Notice of violation from insp on 840822-0911.	8410240233	9/25/1984	2	27137:003-27137:004
Notice of violation from insp on 840912-1017.	8411290419	11/6/1984	2	27721:204-27721:205
Notice of violation from insp on 781101-781201.	7902260054	1/9/1979	1	27761:085-27761:085
Notice of violation from insp on 841120-1220.	8501160537	12/28/1984	1	28420:150-28420:150
Ack receipt of 850124 ltr w/remittance of fee for civil penalty. Corrective actions described in 840615 ltr will be examined during future insps.	8502200013	2/13/1985	2	29016:354-29016:355
Notice of violation from insp on 841221-850215.	8503180118	2/28/1985	1	29419:178-29419:178
Notice of violation from insp on 850219-28.	8504020315	3/27/1985	1	29577:340-29577:340
Notice of violation from insp on 850820-1031.	8511220262	11/15/1985	1	33570:024-33570:024
IE Info Notice 85-097, "Jail Term for Former Contractor Employee Who Intentionally Falsified Welding Insp Records." Svc list encl.	8512230036	12/26/1985	136	34229:001-34229:136
Responds to IE Bulletin 79-03 re welding defects in certain longitudinally welded pipe spools. Plants inspected; no pipe found.	7905250280	4/12/1979	2	45785:001-45785:002
FAILURE OF VALVE TO CLOSE	3001003101	9/5/1973	1	50010-202
INSPECTION OF EMERGENCY PLAN	3001005084	1/11/1974	9	50010-213
INSPECTION OF CORRECTIVE ACTIONS AND NUCLEAR FUEL PROCUREMENT QUALITY ASSURANCE PROGRAM	3001007712	4/2/1974	8	50010-247



INSPECTION OF RADIATION PROTECTION PROCEDURES	3001008101	4/23/1974	15 50010-251
INSPECTION OF OPERATING PROBLEMS INCLUDING ABNORMAL OCCURRENCES	3002003108	9/20/1974	32 50010-309
NOTICE OF VIOLATIONS RADWASTE HISTORY AND NOTICE OF PROPOSED CIVIL PENALTIES CORRECTIONS MADE TO APPARENT NONCOMPLIANCE	3002005295	12/11/1974	12 50010-345
REPLY TO AEC NOTICE OF VIOLATION DATED DECEMBER 11 1974	3002006649	12/30/1974	15 50010-366
SCHEDULE FOR SUBMITTING PROPOSED SPECIFICATIONS BY MAY 5 1975 ON FRACTURE TOUGHNESS	3002006651	2/13/1975	12 50010-368
	3003000334	4/7/1975	1 50010-383
MONTHLY DATA TABLES MARCH 1975 UNIT 2 SHUTDOWN IN MARCH. CORE SPRAY PIPING AND FEEDWATER SPARGER REPLACEMENTS	3003001332	4/2/1975	10 50010-393
INSPECTION OF OPERATIONS AND RECORDS	3003005519	8/28/1975	32 50010-434
INSPECTION OF FACILITY	3003005518	7/18/1975	2 50010-435
INSPECTION OF OPERATIONS AOPES MAINTENANCE PROCEDURES PERSONNEL CAPABILITIES LEAK RATE TEST	3003005516	10/28/1975	27 50010-437
INSPECTION OF RADWASTE SPILL	3003005560	7/25/1975	14 50010-440
IE INSPECTION REPORT NOS. 75-14 75-20 75-16 AND REPLY	3003005687	9/11/1975	24 50010-441
INSPECTION OF PROCEDURES AND RECORDS	3003006905	10/24/1975	2 50010-445
INSPECTION OF PIPE CRACK IN 6 IN. CLEANUP DEMINERALIZER LINE INSERVICE INSPECTION PROGRAM NDE PROCEDURES AND PERSONNEL QUALIFICATION	3003006906	10/28/1975	8 50010-446

STEAM DRUM TO NOZZLE FLOW INDICATION EVALUATION PROGRAM	3003006913	11/17/1975	2 50010-455
INSPECTION OF CRACKS IN PRIMARY COOLING SYSTEM PIPING AND FLAWS IN SAFETY VALVE NOZZLE WELDS	3003006914	11/21/1975	8 50010-456
INSPECTION OF INSERVICE INSPECTION NDE RECORDS 6 INCH CLEAN UP DEMINERALIZER AND UNLOADING HEAT EXCHANGER RETURN LINE	4004000946	12/24/1975	7 50010-466
SEMIANNUAL REPORT JULY-DECEMBER 1975 OPERATING AND MAINTENANCE SECTIONS INSPECTION OF DOCUMENTS RELATING TO REPAIRS OF STEAM DRUM SAFETY ENDS AND ULTRASONIC TEST REPORT ON 6 IN. DEMINERALIZER AND HEAT EXCHANGER	4004002858	2/11/1976	202 50010-499
INSPECTION OF REFUELING PROCEDURES INSPECTION OF RADIOLOGICAL PROTECTION PROCEDURES	4004002862 4004006973	2/11/1976 6/18/1976	6 50010-504 12 50010-546
INSPECTION OF AUDITS UNIT 2 REFUELING STACK RELEASE RATE OF UNIT 1 AND FOLLOW UP ITEMS	4004006977	6/17/1976	23 50010-550
INSPECTION OF ENVIRONMENTAL PROGRAM FOR OPERATION	4005001213	4/28/1976	13 50010-552
INSPECTION OF RADIOACTIVE EFFLUENTS SHIPMENT MONITOR CALIBRATION AND OFF- GAS EXPLOSION	4005001219	7/27/1976	16 50010-564
4005002949		7/8/1976	22 50010-568
SCHEDULE FOR SUBMITTAL OF TS CHANGES ABOUT INSPECTION OF ASME CODE CLASSES 1 2 AND 3 COMPONENTS BY OCTOBER 1976	4005002963	8/20/1976	1 50010-583

INSPECTION OF EMERGENCY PLANNING ONSITE MEDICAL AREA DECON TAMINATION FACILITIES PROCEDURES INVENTORY RECORDS FIRST AID SUPPLIES AND OBSERVATION OF DRILL	4005001705	8/10/1976	8 50010-586
REPLY TO IE INSPECTION REPORT NO. 77-07 -07 AND -07 RE PER SONNEL CONTAMINATION	4006007787	4/27/1977	4 50010-738
CRACK IN PRIMARY PIPING SYSTEM NIPPLE.	3000002633	1/1/1971	2 50010-74
INSPECTION OF RADIOACTIVE WASTE SYSTEMS INSPECTION OF CONFIRMATORY MEASUREMENT PROGRAM FOR RADIOLOGICAL EFFLUENT SAMPLES	4006007790	5/26/1977	11 50010-750
INSPECTION OF OPERATING AND QUALITY ASSURANCE PROCEDURES	4007000428	6/15/1977	8 50010-755
INSPECTION OF CONTAINMENT STRUCTURAL INTEGRITY TEST AND THE INTEGRATED LEAK RATE TEST	4007000449	6/30/1977	9 50010-776
EXAMINATION OF THE CRACK IN THE 4-INCH CLEANUP-DEMINEALIZER PIPING. FINAL REPORT.	4008002113	9/28/1977	8 50010-805
REPLY TO IE INSPECTION REPORT 77-25 RE CONTAINMENT LEAKAGE AIR ENTRAPMENT BELLOWS	3000003277	3/29/1971	29 50010-85
EXAMINATION OF THE CRACK IN THE STUB RISER. FINAL REPORT.	4008005880	10/21/1977	4 50010-858
FURTHER REPLY TO IE INSPECTION REPORT 77- 10 -11 -11 RE COR RECTIVE ACTION FOR MONITORING OF RELEASE RATES OF IODINES INSPECTION OF RADIATION PROTECTION AND EXPOSURE CONTROL	3000003353	3/29/1971	18 50010-86
	4008005886	8/1/1977	1 50010-864
	4008005887	11/4/1977	13 50010-865

INSPECTION OF STEAM SYSTEM PIPE SUPPORTS AND RESTRAINTS	4009001415	1/23/1978	5	50010-910
INSPECTION OF GASEOUS RADIOACTIVE WASTES SYSTEMS	4009001429	3/23/1978	12	50010-934
NON-COMPLIANCE ITEMS RESPONSE TO NRC LETTER OF 3-21-78	4009001702	4/19/1978	13	50010-964
NRC RECEIPT OF CHECK FOR \$21 000 FOR CIVIL PENALTIES	4009001705	5/19/1978	1	50010-967
<No Title>	4584	11/3/1975	1	Q50010-23 (copy frame D4, 1 1 page)
Estimated total page count			1003	