

## SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

GeoLog Well Services, Inc.  
P.O. Box 577  
Wayne City, IL 62895

REPORT NUMBER(S) 2013002

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

150-00012

4. LICENSE NUMBER(S)

IL-022770 / GL under 10 CFR 150.20

5. DATE(S) OF INSPECTION

10/02/13

## LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

## Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Ken Lambert		10/7/13
BRANCH CHIEF	Aaron McCraw		10/8/13

**Docket File Information**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:

GeoLog Well Services, Inc.  
P.O. Box 577  
Wayne City, IL 62895

REPORT NUMBER(S) 2013002

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

150-00012

4. LICENSE NUMBER(S)

IL-022770 / GL under 10 CFR 150.20

5. DATE(S) OF INSPECTION

10/02/13

6. INSPECTION PROCEDURES USED

IMC1220; IP 87123

7. INSPECTION FOCUS AREAS

Appendix III; 03.07

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)

3111

2. PRIORITY

3

3. LICENSEE CONTACT

Greg Pottorff, President/RSO

4. TELEPHONE NUMBER

(618) 315-1540

☒ Main Office Inspection

Next Inspection Date: \_\_\_\_\_

☐ Field Office Inspection \_\_\_\_\_

☐ Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

The licensee is a well logging company located in Wayne City, Illinois with a State of Illinois license that authorized the use of a americium-241/beryllium and cesium-137 sources in the State of Illinois, except in areas of Federal jurisdiction.

This inspection was a follow up for an escalated enforcement action involving the failure to file NRC Form 241 in accordance with 10 CFR 150.20 prior to performing work at temporary job sites in the State of Indian, a Non-Agreement State and an area of exclusive Federal jurisdiction in calendar years 2005 through 2013.

**PERFORMANCE OBSERVATIONS**

The inspector reviewed the corrective actions described in Inspection report No. 15000012/2013001 that included filing NRC Form 241 for Calendar Year 2013, including paying the reciprocity fee; paying the reciprocity fees for Calendar Years 2005-2012; and the RSO stating in a letter, dated March 28, 2013, that he now understands the requirement to file Form 241 prior to working in any non-Agreement State or an area of exclusive Federal jurisdiction. The inspector verified that the licensee paid the reciprocity fee for Calendar Year 2013 and the fees for Calendar Years 2005-2012 by reviewing bank statements showing copies of the checks sent to the NRC. In addition, the RSO stated that the licensee would be adding a calendar reminder in QuickBooks to file for reciprocity in December of each year.

No violations or regulatory requirements were identified.