

BED BATH & BEYOND



Corporate Office

650 Liberty Avenue
Union, NJ 07083
908/688-0888

10-4-13

Director
Office of Federal and State Materials and Environmental Management Programs
ATTN: GLTS
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-0001

**Re: Transfer of Tritium Exit Signs
Bed Bath & Beyond Store #0490, Springfield, MO**

Dear Sir:

Pursuant to Missouri regulation, Bed Bath & Beyond Inc. ("BBB") provides this notice that on September 18, 2013, BBB transferred the self-luminous exit signs listed on the attached table from BBB Store #0490 located at 3308 S. Glenstone Avenue, Springfield, MO 65804, to Shield Source Inc., Attn: Taylor Perry, 925-211C Airport Road, Cavan Monaghan, ON K9J0E7 with license number CNSC # IL-A1-4790.0/2014. For each sign, the manufacturer name, model number, serial number, manufacture date, and original curie content are indicated on the attached tables.

Please contact me at 908-855-4294 if you have any questions regarding this letter or the attached report.

Sincerely,

James O'Connor

Jim O'Connor
Bed Bath & Beyond Inc.
Vice President - Loss Prevention and Safety

Serial Number Spreadsheet (Box Contents)

Store #: 0490 Address: 3308 S Glenstone Ave City, State: Springfield, MO

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>98767A</u> Box <u>1</u> of <u>3</u> Weight of Box: <u>22 lbs</u> Total Curies in this box: <u>48.8 Ci</u>	Do NOT exceed 99 curies per box 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
--	---

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	<u>A274 ISOLITE</u>	<u>07-2002</u>	<u>2040</u>	<u>A27486</u>	<u>6.1 Ci</u>
2	<u>ISOLITE</u>	<u>07-2002</u>	<u>2040</u>	<u>A27486</u>	<u>6.1 Ci</u>
3	<u>ISOLITE</u>	<u>07-2002</u>	<u>2040</u>	<u>A27481</u>	<u>6.1 Ci</u>
4	<u>ISOLITE</u>	<u>07-2002</u>	<u>2040</u>	<u>A27481</u>	<u>6.1 Ci</u>
5	<u>ISOLITE</u>	<u>07-2002</u>	<u>2040</u>	<u>A27483</u>	<u>6.1 Ci</u>
6	<u>ISOLITE</u>	<u>07-2002</u>	<u>2040</u>	<u>A27483</u>	<u>6.1 Ci</u>
7	<u>ISOLITE</u>	<u>07-2002</u>	<u>2040</u>	<u>A27485</u>	<u>6.1 Ci</u>
8	<u>ISOLITE</u>	<u>07-2002</u>	<u>2040</u>	<u>A27485</u>	<u>6.1 Ci</u>
9					
10					

Serial Number Spreadsheet (Box Contents)

Store #: 0490 Address: 3308~~5~~ Glenstone Ave City, State: Springfield, MO

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>9876PA</u> Box <u>2</u> of <u>3</u> Weight of Box: <u>27 lbs</u> Total Curies in this box: <u>48.8 Ci</u>	Do NOT exceed 99 curies per box 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
--	---

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	ISOLITE	07-02	2040	A27484	6.1 Ci
2	ISOLITE	07-02	2040	A27484	6.1 Ci
3	ISOLITE	07-02	2040	A27482	6.1 Ci
4	ISOLITE	07-02	2040	A27482	6.1 Ci
5	ISOLITE	07-02	2040	A27478	6.1 Ci
6	ISOLITE	07-02	2040	A27479	6.1 Ci
7	ISOLITE	07-02	2040	A27476	6.1 Ci
8	ISOLITE	07-02	2040	A27470	6.1 Ci
9					
10					

Serial Number Spreadsheet (Box Contents)

S Glenstone Ave.

Store #: 0490 Address: 3308 ~~Glenstone Ave~~ City, State: Springfield, MO

- Fill out this form for each tritium exit sign going into a box
- Do not exceed 99 curies per box. Seal the box according to the packaging instructions
- FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
- FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: <u>98768A</u> Box <u>3</u> of <u>3</u> Weight of Box: <u>20 lbs</u> Total Curies in this box: <u>30.5</u>	Do NOT exceed 99 curies per box 8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box. Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at <u>less than</u> 100 curies each box)
---	---

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)
1	Isolite	07-02	2040	A27477	6.1 Ci
2	Isolite	07-02	2000	A27474	6.1 Ci
3	Isolite	07-02	2000	A27471	6.1 Ci
4	Isolite	07-02	2040	A27473	6.1 Ci
5	Isolite	07-02	2040	A27480	6.1 Ci
6					
7					
8					
9					
10					

From: (908) 855-4611
Leigh Strothers
BED BATH
650 Liberty Avenue

Origin ID: CDWA



J13201306280326

Union, NJ 07083

Ship Date: 04OCT13
ActWgt: 1.0 LB
CAD: 1447625/INET3430

Delivery Address Bar Code



SHIP TO: (908) 855-4611

BILL SENDER

ATTN: GLTS

U.S. NUCLEAR REGULATORY COMMISSION
OFF OF FED AND STATE MATERIALS

WASHINGTON, DC 20555

Ref # TES
Invoice #
PO #
Dept # 918



MON - 07 OCT AA
STANDARD OVERNIGHT

TRK# 7968 3962 8809

0201

20555
DC-US
IAD

SA NSFA



51AG1/AB1B/1A9E