BEYOND





Corporate Office

650 Liberty Avenue Union, NJ 07083 908/688-0888

10-21-13

Director

Office of Federal and State Materials and Environmental Management Programs ATTN: GLTS
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-0001

Re: Transfer of Tritium Exit Signs

Bed Bath & Beyond Store #0758, Columbus, IN

Dear Sir:

Pursuant to Indiana regulation, Bed Bath & Beyond Inc. ("BBB") provides this notice that on October 02, 2013, BBB transferred the self-luminous exit signs listed on the attached table from BBB Store #0758 located at 1125 N. National Road, Columbus, IN 47201, to Shield Source Inc., Attn: Taylor Perry, 925-211C Airport Road, Cavan Monaghan, ON K9J0E7 with license number CNSC # IL-A1-4790.0/2014. For each sign, the manufacturer name, model number, serial number, manufacture date, and original curie content are indicated on the attached tables.

Please contact me at 908-855-4294 if you have any questions regarding this letter or the attached report.

Sincerely,

Jim O'Connor

Bed Bath & Beyond Inc.

Vice President - Loss Prevention and Safety

I amis Olouum

Store #: 758 Address: 1125 N. National Road City, State: columbus, IN

Fill out this form for each tritium exit sign going into a box
Do not exceed 99 curies per box. Seal the box according to the packaging instructions
FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store
FAX to CB&I at 225-987-3228 BEFORE you leave the store

RMA #: 9892 PA	Do NOT exceed 99 curies per box
Box of 4	8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.
Weight of Box: 22	Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at less than
Total Curies in this box: 9'2	100 curies each box)

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)	PASE
1	Safety Light	9/2003	2000	237 252	11.5	8
2	Sedely Light	9/2003	2000	237252	115	હ
3	Sefet-11:16	9/2003	2000	237257	11.5	7
4	sel liht	9/2003	2000	237257	11.5	7
5	Safory Light	9/2003	2000	2372155	11-5	4
6	Safety light	9/2003	2000	237255	1.5] 7
7	SERVY Light	9/2003	2000	237254	11.5	10
8	Sefectification	9/2005	2000	237254	11.5	10
9	J .	•			×	
10						·

Store #: 758 Address: 1125 N. National Rd City, State: Columbus, IN

Fill out this form for each tritium exit sign going into a box					
Do not exceed 99 curies per box. Seal the box according to the packaging Instructions					
FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store					
FAX to CB&I at 225-987-3228 BEFORE you leave the store					
 D. NOT average Of average was have					

RMA #: 9892 PA	Do NOT exceed 99 curies per box
Box 2 of 4	8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.
Weight of Box: 22	Max of 1,000 curies shipped from one location (this
Total Curies in this box: 92	would be 86 11.6-curie signs or 10 boxes at <u>less than</u> 100 curies each box)

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)	_
1	Schedy Lult	9/2003	2000	237 249	11.5	9
2	Safety light	9/2003	2000	237 249	11.5	9
3	Seffy Light	9/2003	2000	237 256	11.5	13
4	Schedy Light	9/2003	2000	237256	11.5	13
5	SELAN Light	5/2003	2000	224615	11.5] 11
6	Sefety Light	5/2005	2000	224615	11.5]11
7	Safada Light	3/2003	2000	217739	11.5	12
8	Sefety Likt	3/2003	2000	217739	11.5	12
9		· ·				
1.0						

Store #: 758 Address: 1125 N. National R. L. City, State: Columbia IN

☐ Fill out this form for each tritium exit sign going into a box							
□ Do not exceed 99 curies per box. Seal	□ Do not exceed 99 curies per box. Seal the box according to the packaging instructions						
☐ FAX to Taylor Perry at Isolite 610-296	-8952 BEFORE you leave the store						
☐ FAX to CB&I at 225-987-3228 BEFOR	E you leave the store						
RMA #: 9892_PA-	Do NOT exceed 99 curies per box						
Box 3 of 4	8 signs at 11.5 curies each ■ 92 curies = max in a box. 4 signs at 20 curies each ■ 80 curies = max in a box.						
Weight of Box: 22 Total Curies in this box: 92	Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at less than 100 curies each box)						

Line .	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)	BBB#
1	Safely Light	9/2003	2000	237251	115	14
2	Safety Light	9/2003	2000	237251	11.5%	14-
3	Sefect Vight	3/2003	2600	217740	. 11.5	6
4	Safety light	3/2003	2000	2)7740	11.5	6
5	Sold Light	9/2003	2000	237253	11.5	5
6	Sefely light	9/2003	2000	237253	11.5	5
7	Safety Light	9/2003	2000	237256	11.5	15
8	Safety Light	9/2003	2000	237250	11-2	15
9						
10						

Store #: 756 Address: 1125 N. National Killity, State: Columbus, IN

☐ Fill out this form for each tritium e	oxit sign going into a box							
□ Do not exceed 99 curies per box.	Do not exceed 99 curies per box. Seal the box according to the packaging instructions							
☐ FAX to Taylor Perry at Isolite 61	☐ FAX to Taylor Perry at Isolite 610-296-8952 BEFORE you leave the store							
☐ FAX to CB&I at 225-987-3228 BI	☐ FAX to CB&I at 225-987-3228 BEFORE you leave the store							
RMA#: 9892 PA-	Do NOT exceed 99 curies per box							
Box 4 of A	8 signs at 11.5 curies each = 92 curies = max in a box. 4 signs at 20 curies each = 80 curies = max in a box.							
Weight of Box:	Max of 1,000 curies shipped from one location (this would be 86 11.5-curie signs or 10 boxes at less than 100 curies each box)							
Λ.	would be 86 11.5-curie signs or 10 boxes at less than							

Line	Manufacturer Name	Manufacture Date	Model #	Serial #	Activity(Ci or TBq amount) (Number of Curies)	BBB#
1	Safety Light	9/2003	2000	238526	11-5	16
2	Sefety Light	9/2003	2040	237245	Ĩ1-5] 1
3	Safely (ight	9/2003	2040	238528	11.5]3
4	Safety Light	9/2003	2040	237297	11.5	2
5						
6]
7]
8						[
9						1
10				·	·] .

From: (908) 855-4611 Leigh Strothers BED BATH 650 Liberty Avenue

SHIP TO: (908) 855-4611

ATTN: GLTS

Union, NJ 07083

Origin ID: CDWA

Ship Date: 210CT13 ActWgt: 1.0 LB CAD: 1447625/INET3430



BILL SENDER

Delivery Address Bar Code

918



Ref#

P0# Dept#

Invoice # U.S. NUCLEAR REGULATORY COMMISSION

WASHINGTON, DC 20555

OFF OF FED AND STATE MATERIALS


TRK# 0201


7969 5497 4680

TUE - 22 OCT AA STANDARD OVERNIGHT

> 20555 DC-US IAD

EP NSFA





- 1. Use the 'Print' button on this page to print your label to your laser or inkjet printer.
- 2. Fold the printed page along the horizontal line.
- 3. Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned.

Warning: Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number. Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com.FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, nondelivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$1,000, e.g. jewelry, precious metals, negotiable instruments and other items listed in our ServiceGuide. Written claims must be filed within strict time limits, see current FedEx Service Guide.