

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8711170098 DOC. DATE: 87/11/09 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
 AUTH. NAME AUTHOR AFFILIATION
 MORGAN, H. E. Southern California Edison Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Supplemental special rept on 870821, exam of steam generator
 E-088 revealed two metal pieces lodged between tubes in
 periphery. Objects appear to have been in generator since
 const. Metal pieces removed & tubes examined.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1	PD5 PD	1
	ROOD, H	1		
INTERNAL:	ACRS MICHELSON	1	ACRS MOELLER	2
	AEOD/DOA	1	AEOD/DSP/NAS	1
	AEOD/DSP/ROAB	2	AEOD/DSP/TPAB	1
	ARM/DCTS/DAB	1	DEDRO	1
	NRR/DEST/ADS	1	NRR/DEST/CEB	1
	NRR/DEST/ELB	1	NRR/DEST/ICSB	1
	NRR/DEST/MEB	1	NRR/DEST/MTB	1
	NRR/DEST/PSB	1	NRR/DEST/RSB	1
	NRR/DEST/SGB	1	NRR/DLPQ/HFB	1
	NRR/DLPQ/QAB	1	NRR/DOEA/EAB	1
	NRR/DREP/RAB	1	NRR/DREP/RPB	2
	NRR/DRIS/SIB	1	NRR/PMAS/ILRB	1
	<u>REG FILE</u> 02	1	RES DEPY GI	1
	RES TELFORD, J	1	RES/DE/EIB	1
	RGN5 FILE 01	1		
EXTERNAL:	EG&G GROH, M	5	H ST LOBBY WARD	1
	LPDR	1	NRC PDR	1
	NSIC HARRIS, J	1	NSIC MAYS, G	1



Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN
STATION MANAGER

November 9, 1987

TELEPHONE
(714) 368-6241

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Docket No. 50-361
Special Report Supplementary Information
Inservice Inspection of Steam Generator Tubes
San Onofre Nuclear Generating Station, Unit 2

Reference: Letter from H. E. Morgan (SCE) to USNRC Document Control Desk
dated October 5, 1987

This report is being submitted to the Commission to provide information associated with a supplemental examination of steam generator E-088 at San Onofre Unit 2 resulting from the discovery of two foreign objects in the steam generator.

As reported in the reference, eddy current inspection of the steam generator tubing was completed on September 21, 1987. Subsequent to the completion of sludge lancing, visual inspection of the secondary side on both steam generators was conducted. On steam generator E-088, the inspection found two metal pieces lodged between the tubes in the periphery near the tubesheet. Although the source of the material has not been identified, due to the size of the metal pieces, it is believed these objects have been in the steam generator since original construction. No foreign objects were found on steam generator E-089.

The metal pieces were removed and 155 steam generator tubes surrounding the location of the metal pieces were examined through the first outlet end tube support using eddy current testing. One of the tubes examined was determined to be defective and was removed from service by mechanical plugging.

8711170098 871109
PDR ADOCK 05000361
S PDR

IE22
A047
110

If you require any additional information, please so advise.

Sincerely,

JEM

cc: J. B. Martin (Regional Administrator, USNRC Region V)
F. R. Huey (USNRC Senior Resident Inspector, Units 1,2 and 3)
H. Rood (Project Manager, SONGS 2/3, USNRC, NRR)

Institute of Nuclear Power Operations (INPO)