

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9001030015 DOC. DATE: 89/12/20 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern Californ 05000362

AUTH. NAME AUTHOR AFFILIATION
 NANDY, F.R. Southern California Edison Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Informs that followup info re MSSV will be further delayed until 900130.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	PD5 LA	1	1	PD5 PD	1	1
	KOKAJKO, L.	5	5			
INTERNAL:	ACRS	6	6	NRR/DET/ECMB 9H	1	1
	NRR/DOEA/OTSB11	1	1	NRR/DST 8E2	1	1
	NRR/DST/SELB 8D	1	1	NRR/DST/SICB 7E	1	1
	NRR/DST/SRXB 8E	1	1	NUDOCS-ABSTRACT	1	1
	OC/LFMB	1	0	OGC/HDS2	1	0
	<u>REG FILE</u> 01	1	1	RES/DSIR/EIB	1	1
EXTERNAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 27 ENCL 25-0

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S

MA-4



Southern California Edison Company

23 PARKER STREET
IRVINE, CALIFORNIA 92718

December 20, 1989

F. R. NANDY
MANAGER OF NUCLEAR LICENSING

TELEPHONE
(714) 587-5400

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
Main Steam Safety Valve Analysis
San Onofre Nuclear Generating Station
Units 2 and 3

The purpose of this letter is to inform you that the follow-up information regarding the San Onofre Nuclear Generating Station, Units 2 and 3, Main Steam Safety Valves (MSSV) will be further delayed until January 30, 1990. As was discussed in October with the NRC Project Manager, the blowdown and overpressure analytical work for both Units 2 and 3 was in progress. Since then, the analytical work to change from factory ring settings to generic ring settings for Unit 2 has been completed satisfactorily. However, the analysis for Unit 3 is still undergoing final review. Thus, the report was not completed in time to meet the December 15, 1989 date as we had indicated in our letter of October 26, 1989, and necessitates the further delay.

If you have any questions, please feel free to call me.

Very truly yours,

cc: J. B. Martin, Regional Administrator, NRC Region V
C. Caldwell, NRC Senior Resident Inspector, San Onofre Units 1, 2 and 3

9001030015 891220
PDR ADOCK 05000361
PDC

A001
1/0