

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME:

01	C	A	S	0	S	I
----	---	---	---	---	---	---

 LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 EVENT TYPE:

0	3
---	---

CATEGORY:

CON'T

 REPORT TYPE:

L

 REPORT SOURCE:

L

 DOCKET NUMBER:

0	5	0	-	0	2	0	6
---	---	---	---	---	---	---	---

 EVENT DATE:

0	5	2	0	7	6j
---	---	---	---	---	----

 REPORT DATE:

0	6	0	9	7	6
---	---	---	---	---	---

EVENT DESCRIPTION

02

 At 12:45 a.m. on May 20, 1976, while operating at full power "B" Steam Generator indicated steam flow started decreasing on a slow ramp. The steam flow indication stabilized at approximately 85% of full load steam flow. "B" steam generator feedwater flow was transferred from automatic to manual control with an operator at continuous attendance at the controls. At approximately 9:45 a.m. a sphere entry was made and the blowdown valve on the high pressure line to the steam flow transmitter was found to be leaking. A plug was installed which corrected the leak. At the first convenient outage the valve will be replaced to prevent a recurrence.

SYSTEM CODE:

H	B
---	---

 CAUSE CODE:

F

 COMPONENT CODE:

X	X	X	X	X	X
---	---	---	---	---	---

 PRIME COMPONENT SUPPLIER:

N

 COMPONENT MANUFACTURER:

W	1	2	0
---	---	---	---

 VIOLATION:

N

CAUSE DESCRIPTION

08

 Discussed in the "Event Description" above.

FACILITY STATUS:

E

 % POWER:

1	0	0
---	---	---

 OTHER STATUS:

NA

 METHOD OF DISCOVERY:

a

 DISCOVERY DESCRIPTION:

NA

FORM OF ACTIVITY RELEASED:

Z

 CONTENT OF RELEASE:

Z

 AMOUNT OF ACTIVITY:

NA

 LOCATION OF RELEASE:

NA

PERSONNEL EXPOSURES

NUMBER:

0	0	0
---	---	---

 TYPE:

Z

 DESCRIPTION:

NA

PERSONNEL INJURIES

NUMBER:

0	0	0
---	---	---

 DESCRIPTION:

NA

OFFSITE CONSEQUENCES

15

NA

LOSS OR DAMAGE TO FACILITY

TYPE:

Z

 DESCRIPTION:

NA

PUBLICITY

17

 Event occurrence released to standard publicity list.

ADDITIONAL FACTORS

18

NA

19

NAME: H. L. Ottoson PHONE: 714-492-7700

P1030605102