

Southern California Edison Company

SE

P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

JACK B. MOORE
VICE PRESIDENT

TELEPHONE
213-572-2292

June 22, 1979

Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, California 94596

Dear Mr. Engelken:


Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station, Units 2 and 3

By letter dated January 23, 1979, we confirmed notification concerning a reportable condition in construction of San Onofre Units 2 and 3 related to surface defects in carbon steel pipe manufactured by Taylor Forge. An interim report on this condition was forwarded by our letter dated February 22, 1979.

Enclosed in accordance with 10CFR50.55(e) are twenty-five (25) copies of a final report entitled "Final Report on Taylor Forge Pipe Defects, San Onofre Nuclear Generating Station, Units 2 and 3."

If you have any questions regarding this report, we would be pleased to discuss this matter with you at your convenience.

Very truly yours,



Enclosure

cc: John G. Davis (NRC, Acting Director I&E)
R. J. Pate (NRC, San Onofre)

7907100676

5