

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912200541 DOC. DATE: 79/12/14 NOTARIZED: NO DOCKET #  
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern California 05000361  
 50-362 San Onofre Nuclear Station, Unit 3, Southern California 05000362

AUTH. NAME AUTHUR AFFILIATION  
 ARENAL, A. Southern California Edison Co.  
 RECIPIENT NAME RECIPIENT AFFILIATION  
 ENGELKEN, R.H. Region 5, San Francisco, Office of the Director

SUBJECT: Forwards interim deficiency rept re lack of documentation for measuring & test equipment.

DISTRIBUTION CODE: B019B COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+3  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: SEND ALL FSAR & ER AMENDS TO L. CHANDLER.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES		
	ID CODE/NAME	LTTR	ENCL		ID CODE/NAME	LTTR	ENCL
ACTION:	14 PM <u>ROOD</u>	1	1	15 BC <u>LWR #2</u>	1	1	
	20 LA <u>LWR #2</u>	1	1	21 AD <u>LWR</u>	1	1	
INTERNAL:	01 <u>REG FILE</u>	1	1	02 NRC PDR	1	1	
	05 I&E	2	2	07 EDU & STAFF	1	1	
	08 MPA	1	1	09 DEPY DIR DPM	1	1	
	10 GAB	1	1	11 STANDRDS DEV	1	1	
	12 JORDAN, E/IE	1	1	13 FIELD COOR/IE	1	1	
	16 AD FOR ENGR	1	1	17 AD PLANT SYS	1	1	
	17 AD REAC SFTY	1	1	22 DIR DPM	1	1	
	23 OELD	1	1	AD/SITE TECH	1	1	
	DIRECTOR DSE	1	1	GEOSCIENCES BR	1	1	
	I&C SYS BR	1	1	MATL ENG BR	1	1	
	MECH ENG BR	1	1	POWER SYS BR	1	1	
	S HANAUER	1	1	STRUCT ENG BR	1	1	
	EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
		24 ACRS	16	16			

Ltr  
 MOORE  
 EPB #2 BC  
 D. SCALETTI  
 EPB #2 LA

DEC 27 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 51 ENCL 47

GD  
 MA<sub>2</sub>

Southern California Edison Company



P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

A. ARENAL  
VICE PRESIDENT

TELEPHONE  
213-572-1476

December 14, 1979

Mr. R. H. Engelken, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region V  
Suite 202, Walnut Creek Plaza  
1990 North California Boulevard  
Walnut Creek, California 94596

Dear Mr. Engelken:

Subject: Docket Nos. 50-361 and 50-362  
San Onofre Nuclear Generating Station, Units 2 and 3

In a letter to your office dated November 14, 1979, we identified a condition which we consider reportable in accordance with 10CFR50.55(e). This condition involves the lack of "as-received" documentation for some inspection, measuring and test equipment sent to vendors for recalibration.

Enclosed in accordance with 10CFR50.55(e) are twenty-five (25) copies of an interim report entitled "Interim Report on Measuring and Test Equipment Recalibrated at Vendor Facilities, San Onofre Nuclear Generating Station, Units 2 and 3." By February 15, 1980, we will advise you of the submittal date of the final report.

If you have any question regarding this report, we would be pleased to discuss this matter with you at your convenience.

Very truly yours,

*A. Arenal*

Enclosures

cc: Victor Stello (NRC, Director I&E) ✓  
R. J. Pate (NRC, San Onofre Units 2 and 3)

BO19  
SE  
1/1

7912200541