

6/13/79

DISTRIBUTION:

Docket 50-206

GErtter(EDO-06730)

NRC PDR

MGroff

Local PDR

JMullin

EDO RDG

DEisenhut

NRR RDG

RVollmer

ORB#2 RDG

WRussell

LGossick

BGrimes

DMuller

TCarter

ECase

DLZiemann

HDenton

WGammill

TRehm

ABurger

FSchroeder

HSmith

DVassallo

SEP/AD RDG(EDO-06730)

Attorney, OELD

OCA(3)

See 79-1931

JUL 20 1979

Docket No. 50-206

Ms. Sylvia M. Siegel
Executive Director
Toward Utility Rate Normalization
693 Mission Street, 8th Floor
San Francisco, California 94105

Dear Ms. Siegel:

This is in response to your letter dated June 21, 1979, to the Chairman of the Nuclear Regulatory Commission. You requested a copy of a report submitted to us by Southern California Edison Company (the licensee) with respect to pipe cracks that resulted in a shutdown of the San Onofre Unit 1 facility.

Enclosed is an Interim Report titled, "San Onofre Unit 1 Steam Generator Nozzle to Piping Inspection and Corrective Action," dated June 13, 1979, including the transmittal letter dated June 15, 1979 (from J. Moore to R. Engelken) and the related Licensee Event Report No. 79-010. This report provides information pertaining to the licensee's evaluation of indications of flaws discovered in the Feedwater System piping at San Onofre Unit 1 on June 5, 1979.

It should be noted that the indication of flaws in the Feedwater System piping did not result in a shutdown of the San Onofre Unit 1 facility. The indications of flaws were discovered during a shutdown of the facility initiated by the licensee to repair a steam generator leak. However, repair of the Feedwater System piping, as a result of the indications of flaws, did prolong the shutdown.

We expect the licensee to submit a final report as soon as it has completed its investigations. We will forward you a copy of this report when it is available.

Sincerely,

Original Signed by
H. R. Denton

79088300 154 *cap*

*See previous yellow concurrence

Harold R. Denton, Director
Office of Nuclear Reactor Regulation

DOR:ORB#2 DOR:ORB#2

*HSmith:sah *ABurger

Enclosure: 7/ /79 7/ /79

As stated

OFFICE	DOR:ORB#2	DOR:A/AD-SEP	OELD	DOR:DIR	NRR:DIR	NRR:OR
SURNAME	*DLZiemann	*RHVollmer	*	DGEisenhut	EGCase	HRDenton
DATE	7/ /79	7/ /79	7/ /79	7/10/79	7/14/79	7/19/79

DISTRIBUTION:

Docket 50-206
NRC PDR
Local PDR
EDO RDG
NRR RDG
ORB#2 RDG
LGossick
DMuller
ECase
HDenton
TRehm
FSchroeder
DVassallo
Attorney, OELD
OCA(3)

GErtter(EDO-06730)
MGroff
JMullin
DEisenhut
RVollmer
WRussell
BGrimes
TCarter
DLZiemann
ABurger
HSmith
S&P RDG(EDO-06730)

W. Gammill

Docket No. 50-206

Mrs. Sylvia M. Siegel
Executive Director
Toward Utility Rate Normalization
693 Mission Street, 8th Floor
San Francisco, California 94105

Dear Mrs. Siegel:

This is in response to your letter dated June 21, 1979, to the Chairman of the Nuclear Regulatory Commission. You requested a copy of a report submitted to us by Southern California Edison Company (the licensee) with respect to pipe cracks that resulted in a shutdown of the San Onofre Unit 1 facility.

Enclosed is an Interim Report titled, "San Onofre Unit 1 Steam Generator Nozzle to Piping Inspection and Corrective Action," dated June 13, 1979, including the transmittal letter dated June 15, 1979 (from J. Moore to R. Engelken) and the related Licensee Event Report No. 79-010. This report provides information pertaining to the licensee's evaluation of indications of flaws discovered in the Feedwater System piping at San Onofre Unit 1 on June 5, 1979.

We expect the licensee to submit a final report when the metallurgical investigations have been completed. We will forward you a copy of this report when it is available.

Sincerely,

Harold R. Denton, Director
Office of Nuclear Reactor Regulation

Enclosure:
As stated

DOR:ORB#2
H...:sah
7/1/79
DOR:ORB#2
ABurger
7/1/79

Enclosure conditions on addition.

OFFICE >	DOR:ORB#2	DOR:AD/S&P	OELD	DOR:A/DIR	NRR:D/DIR	NRR:DIR
SURNAME >	DLZiemann	RVollmer	McGowan	DGEisenhut	EGCase	HRDenton
DATE >	7/1/79	7/1/79	7/1/79	7/1/79	7/1/79	7/1/79



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

Docket No. 50-206

MS.
Mrs. Sylvia M. Siegel
Executive Director
Toward Utility Rate Normalization
693 Mission Street, 8th Floor
San Francisco, California 94105

Dear *MS.* Mrs. Siegel:

This is in response to your letter dated June 21, 1979, to the Chairman of the Nuclear Regulatory Commission. You requested a copy of a report submitted to us by Southern California Edison Company (the licensee) with respect to pipe cracks that resulted in a shutdown of the San Onofre Unit 1 facility.

Enclosed is an Interim Report titled, "San Onofre Unit 1 Steam Generator Nozzle to Piping Inspection and Corrective Action," dated June 13, 1979, including the transmittal letter dated June 15, 1979 (from J. Moore to R. Engelken) and the related Licensee Event Report No. 79-010. This report provides information pertaining to the licensee's evaluation of indications of flaws discovered in the Feedwater System piping at San Onofre Unit 1 on June 5, 1979.

We expect the licensee to submit a final report *as soon as it has completed its* when the metallurgical investigations ~~have been completed~~. We will forward you a copy of this report when it is available.

Sincerely,

Harold R. Denton, Director
Office of Nuclear Reactor Regulation

Enclosure:
As stated

It should be noted that the indications of flaws in the Feedwater System piping did not result in a shutdown of the San Onofre Unit 1 facility. The indications of flaws were discovered during a shutdown of the facility, initiated by the licensee to repair a steam generator leak. However, repair of the Feedwater System piping, as a result of the indications of flaws, did prolong the shutdown.