


Central Files

Southern California Edison Company

SCE

January 2, 1980



U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
Suite 202, Walnut Creek Plaza  
1990 North California Boulevard  
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Docket No. 50-206  
San Onofre Unit 1

Dear Sir:

IE Bulletin 79-28  
Possible Malfunction of  
Namco Model EAL80 Limit  
Switches at Elevated  
Temperatures

Reference is made to your correspondence of December 7, 1979, forwarding the subject IE Bulletin. This bulletin identified potential malfunctions of Namco Model EAL80 stem mounted limit switches.

A review of Namco EAL80 limit switches installed or being installed at Unit 1 found no Namco limit switches which have an identification number between 02-79 to 08-79. Therefore, the corrective action required by Bulletin 79-28 does not apply.

If you have any questions or desire additional information concerning our response to IE Bulletin 79-28, please contact me.

Sincerely,

  
R. Dietch  
Vice President

cc: Director, Office of Inspection and Enforcement

8002280 250

for  
80-01