REGULATORY DEKET FILE COPY

mõ

MAY 2 0 1980

Docket No.: 50-206

MEMORANDUM FOR:

Harold R. Denton, Director Office of Nuclear Reactor Regulation

FROM:

Victor Stello, Jr., Director Office of Inspection and Enforcement

SUBJECT:

STEAM GENERATOR TUBE SUPPORT PLATE CRACKING -SOUTHERN CALIFORNIA EDISON'S SAN ONOFRE UNIT 1

Your office requested that IE make an inquiry into whether safety information had been withheld from the regulatory staff regarding steam generator tube support plate cracking at Southern California Edison's San Onofre Unit 1. This request was contained in a memorandum from E. G. Case to E. Volgenau dated April 5, 1978.

A special team of IE inspectors performed the requested inquiry which included: interviews of NRC, Westinghouse, EDS, and Southern California Edison personnel and collection and review of pertinent photographs and documents. The report of the results of the inquiry made by the team is enclosed.

Based on their review of the results of the inquiry the team was unable to establish that the licensee did intentionally withhold safety information from the regulatory staff. Further, the team was unable to establish that the regulatory staff did ask the licensee whether the San Onofre Unit 1 steam generators had experienced flow slot cracking similar to that experienced elsewhere.

As a result of the investigation findings, we had considered the issuance of a Notice of Violation to the licensee. We find, however, that the investigation report does not clearly establish noncompliance. We see no need for further action at this time and have closed the inquiry.

"Original Signed By R. C. DeYoung"

· · ·	no	onel.	Direct Dffice	Stello, Jr. or of Inspection Enforcement	n 	Telecontra Come horan BackerD
	Nosure: As st AC:PAB.RCI	ated ;	xoos M	AD: IEA	D: IED for	ELD
•	JEGag/iardo:	HDThornburg	DThompson	RCDeroung	VStello	Bach /h &
DATE	5/ / 80	-5/··¥····/80·····	.5./	5/	.5/ <i>HD</i> /.80	5/20/80
IEC FORM 318 (9-76) NRCM 0240						

8006090 858