

APPENDIX B

NOTICE OF DEVIATION

Southern California Edison Company
San Onofre Unit 2

Docket No. 50-361
License No. NPF-10

As a result of the inspection conducted during the period March 23 through May 21, 1985, a deviation from one of your commitments to the NRC was identified. In accordance with the General Statement of Policy and Procedure for NRC Enforcement Actions, 10 CFR Part 2 Appendix C, as revised, 49 FR 8583 (March 8, 1984), the deviation is set forth below:

Paragraph 6.2.2.1.2.3.c of the FSAR states, in part:

"6.2.2.1.2.3.c Operating During Shutdown Cooling To preclude diverting shutdown cooling flow to the containment spray header, the header isolation valves (HV-9367 and HV-9368) are closed and power to their operators is locked out."


Contrary to the above commitment, the spray header isolation valves (HV-9367 and HV-9368) did not have power removed from their operators during shutdown cooling operation on February 27, 1985.

This is a deviation applicable to Unit 2.

You are hereby requested to submit to this office within thirty days of the date of this notice a written statement regarding the above deviation, describing corrective steps taken, the results achieved (or corrective steps that are planned) and the date when corrective action will be completed.

JUL 31 1985

Dated



P. H. Johnson, Chief
Reactor Projects Section 3

8508200671 850731
PDR ADOCK 05000206
Q PDR