Southern California Edison Company P. O. BOX 800 2244 WALNUT GROVE AVENUE ROSEMEAD, CALIFORNIA 91770 TELEPHONE M. O. MEDFORD (818) 302-1749 MANAGER, NUCLEAR LICENSING July 2, 1986 Director of Nuclear Reactor Regulation Attention: G. E. Lear, Director Project Directorate No. 1 Division of PWR Licensing - A U. S. Nuclear Regulatory Commission Washington, D.C. 20555 Gentlemen: Docket No. 50-206 Subject: Implementation of Generic Requirements San Onofre Nuclear Generating Station Unit 1 Your letter dated April 30, 1986 requested that we assist you in providing information for the Regulatory Information Tracking System. In the enclosed we have provided the status of the issues and the dates of completion or scheduled completion. For those issues where Licensee Status and Date has not been provided, additional information is needed from the NRC Project Manager to better define the issue such that a status can be provided. If you have any questions regarding the enclosure, please let me know. Very truly yours, m. O. medf d Enclosure 8607080195 860702 PDR ADDCK 05000206

REGULATORY INFORMATION TRACKING SYSTEM

FACILITY IMPLEMENTATION

FACILITY: SAN ONOFRE 1

PLANT LOCATION: DOCKET NUMBER:

5 MI S OF SAN CLEMENTE,

ARCH/ENGINEER: BECH

A. DANGELO IE INSPECTOR:

050-00206

DESIGN POWER: 0436 MWE NSSS VENDOR:

LICENSED POWER: 1347 MWT

WEST

PROJECT MANAGER: R. DUDLEY BRANCH CHIEF: G. LEAR

LIC. ASSISTANT: P. SHUTTLEWORTH

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	<u>LICENSEE</u> STATUS	DATE
M07099	A01	10 CFR 50.55 A(G) - ISI	09/26/79C	1978 Program in effect; update scheduled fo	or 1989
M08101	A-02	APPENDIX I - ALARA	08/27/84C	1/1/85 T.S. Effective; Mods completed by RT	TS 6/86
M07079	A03	SECURITY REVIEWS-MODIFIED AMENDMENT PLANS	04/10/79C	Revision 9 under NRC Review	SCE letter 5/8/86
MO8592	A-04	APPENDIX J - CONTAINMENT LEAK TESTING	08/03/82C	TS issued 6/4/84 and 2/8/85; additional in	fo on leakage criteria to
				be submitted	
MO8448	A-06	RESPIRATORY PROTECTION SYSTEM	11/27/78C	Completed	NRC Letter 11/27/78
M10153	A09	PRESSURE VESSEL BELTLINE MATERIAL SURVEILLANCE	01/11/81C	Capsule scheduled to be removed	1988 Refueling outage
M10588	A-10	CONTINGENCY PLANNING	01/22/81C	Revision 1A approved	NRC letter 9/6/85
M10587	A11	GUARD TRAINING PLANS	01/22/81C	Revision 4 approved	NRC letter 1/14/86
M10584	A-12	VITAL AREA ANALYSIS	04/12/82C		
M11231	A-14	10 CFR 50.55 A(G) - INSERVICE TESTING	04/01/86C	IST program in effect; SCE letter 3/3/86 u	nder NRC review
M12557	A-15	QUALITY ASSURANCE REQUEST REGARDING DIESEL GENARAT	04/14/80C		
M51130	A-17	INSTRUMENTATION TO FOLLOW THE COURSE OF AN ACCIDENT	09/30/86	Under NRC review	SCE letter 12/16/85
M59138	A-20	10 CFR 50.62 OPERATING REACTOR REVIEWS	09/30/86	Modifications to be implemented in accorda	nce with ILS
M59980	A21	10 CFR 50.61, PRESSURIZED THERMAL SHOCK RULE	07/31/86	Analysis completed	SCE submittal 1/23/86
MO6766	B-02	FIRE PROTECTION	07/19/79C	To be completed by RTS	6/86
M08399	B-03	PWR MODERATOR DILUTION	02/21/79C	Completed with TS issuance	NRC SER 4/23/84
MO6836	B-04	REACTOR VESSEL OVERPRESSURE PROTECTION	10/27/82C	System completed; T.S. Under NRC Review	SCE letter 1/21/86
M07808	B-07	STEAM GENERATOR FEEDWATER FLOW INSTABILITY	01/20/81C		
M07849	B-09	CHARGING SYSTEMS PIPE VIBRATIONS	09/25/79C	Completed evaluation 4/20/79	NRC letter 9/25/79
M07966	B11	FLOOD OF EQUIPMENT IMPORTANT TO SAFETY	03/18/81C	Bellows sleeve completed; CST Analysis com	pleted 5/19/86

FACILITY: SAN ONOFRE 1 (CONTINUATION)

TAC NO.	MPA #	TIPLE	LIC ACT	<u>LICENSEE</u> STATUS	DATE
M06492	8-12	STEAM GENERATOR TUBE INSPECTION	10/31/78C	Insp. completed; deleted 3.E by NRC SER 10	
MO8174	B-14	CEA GUIDE TUBE WEAR	07/10/80C	No action required; completed with	NRC Letter 7/10/80
				NRC review	
M12133	B-16	EMERGENCY PLANNING AND REVISIONS	04/01/81C	Completed with NRC audit	NRC letter 5/9/83
M10815	8-17	TECH SPEC SURVEILLANCE FOR HYDRAULIC SNUBBERS	09/08/82C	T.S. issued NRC letter 10/15/84; remove ex	emption for testing large
				bore snubbers	
M10289	B-20	CONTAINMENT LEAKAGE DUE TO SEAL DETERIORATION	03/25/81C	Completed with approval of SCE	NRC letter 02/17/84
				letter 1/26/83	
M10351	B-21	LOSS OF 125-V DC BUS VOLTAGE W/LOSS OF ANNUNCIA	04/29/81C		
M10152	B-22	TECH SPEC SURVEILLANCE REQUIREMENTS FOR MECHANICAL	09/08/82C	Completed with issuance of T.S.	NRC letter 10/15/84
M10051	B-23	DEGRADED GRID VOLTAGE	06/23/82C	Modifications to be implemented in accorda	nce with ILS
M42615	B-24	VENTING AND PURGING CONTAINMENTS WHILE AT FULL POWER	02/17/84C	Vent line use under NRC Review	SCE letter 1/21/86
M10189	B-24	VENTING AND PURGING CONTAINMENTS WHILE AT FULL POWER	03/15/81C	Completed with issuance of T.S.	NRC letter 02/17/84
M10245	B26	INADVERTANT SAFETY INJECTION DURING COOL DOWN	09/14/79C		
M49431	8-32	BLOCKED SI SIGNAL DURING COOL DOWN	02/08/83C	Completed by NRC acceptance of config.	NRC letter 12/6/82
M08046	B37	STEAM GENERATOR TUBE DENTING AND SUPPORT PLATE MOD	10/31/78C	Completed with issuance of T.S.	NRC SER 10/31/78
M08693	8-39	PWR PRESSURE - TEMPERATURE LIMIT TECH SPECS	11/13/80C	Completed with T.S. issuance	NRC SER 5/21/86
M11114	B-41	FIRE PROTECTION - (INCLUDES SER S	02/04/81C	Mods to be completed by RTS	6/86
M48143	8-41	FIRE PROTECTION - (INCLUDES SER S	11/18/82C	Superceded by NRC SER 5/15/86	
M47498	B-41	FIRE PROTECTION - (INCLUDES SER S	03/05/82C	Determined emergency lights not needed	NRC SER 5/15/86
M11696	B-42	TMI FOLLOW UP - ALL PLANTS	06/19/81C	No SCE action required	
M11825	B-43	PWR FEEDWATER LINE CRACKS	02/26/80C	Cracks repaired and inspected; completed	NRC letter 02/26/80
				with NRC approval	

FACILITY: SAN ONOFRE 1

TAC NO.	MPA #	TTILE	LIC ACT COMPLETE	<u>LICENSEE</u> STATUS	DATE
M43151	B43	PWR FEEDWATER LINE CRACKS	05/25/82C	Completed	
M12439	B-14	LESSONS LEARNED IMPLEMENTATION	05/02/80C	NRC audit and review completed for 0578	NRC letter 5/2/80
M30570	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending	6/17/81
M30571	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending	6/17/81
M30572	B44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending 6/17/81; 7	r.S. in effect 12/16/81
M30573	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed by station order issued	1/1/80
M30574	B44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed by station order issued	1/2/80
M30575	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Program implemented in outage ending	6/17/81
M30576	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending	6/17/81
M30577	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending	6/17/81
M30578	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending 6/17/81	NRC SER 4/18/83
M30579	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed study 1/17/80; completed mods in	outage ending 6/17/81
M30580	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending	6/17/81
M30581	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending	6/17/81
M30582	B-44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Completed mods in outage ending	6/17/81
M30583	B44	LESSONS LEARNED IMPLEMENTATION	05/02/80C	Participated in WOG/EPRI program	1/80
M12920	B45	WASH 1400 EVENT V, "PRIMARY COOLANT SYSTEM PRESSURE	O3/O3/81C	Completed with T.S. issuance	NRC order 4/20/81
M12582	B-46	ANALYSIS OF TURBINE DISC CRACKS	O3/24/82C	Completed with SCE agreement to use	SCE letter 03/24/82
				inspection criteria	٠
M48388	B-48	ADEQUACY OF STATION ELECTRIC DISTRIBUTION VOLTAGE	05/27/83C	Under NRC Review	SCE letter 12/4/85
M42131	B-57	DHR CAPABILITY	07/06/84	Completed by issuance of T.S.	10/4/84 T.S. Effective
M42916	B59	MASONRY WALL DESIGN	11/07/85C	Analyses and tests performed;	NRC SER 11/7/85
				Completed with NRC approval	

FACILITY: SAN ONOFRE 1

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	<u>LICENSEE</u> STATUS	DATE
M42516	B60	ENVIRONMENTAL QUALIFICATION	03/11/85C	To be completed by RTS	6/86
M42706	B-61	LOSS OF NON CLASS IE I&C POWER	07/22/82C		
M42777	B-62	ESF RESET CONTROL DESIGN DEFICIENCY	10/05/82C	Modifications to be implemented in accorda	ance with ILS
M43939	B-63	INTERIM PROCEDURES FOR SHORT TERM BLACKOUT	12/17/81C	Completed by emergency procedures	SCE letter 7/21/81
M47169	B66	NATURAL CIRCULATION COOL DOWN	08/09/83C	WOG analysis completed 4/10/81;	NRC SER 8/9/83
				NRC concurs with SCE evaluation	
M47549	8-67	THERMAL SHOCK	02/02/83C	Analysis completed	SCE letter 1/25/82
M47030	B67	THERMAL SHOCK	01/21/82C	Analysis completed	SCE letter 11/4/81
M46861	8-69	IEB 80-4 MAINSTEAM LINE BREAK WITH CONTINUED FEEDW	09/27/82C	Completed evaluation; approved by	NRC SER 9/27/82
M49756	B-72	NUREG 0737 TECH SPECS (GENERIC LETTER 82-16)	11/02/84C	Completed with issuance of T.S.	NRC SER 11/2/84
M52797	B-76	ITEM 1.1 - POST TRIP REVIEW; PROGRAM DESCRIPTION &	05/09/85C	Completed with NRC approval of program	NRC SER 5/9/85
M52878	B-77	ITEM 2.1 - EQUIPMENT CLASSIFICATION & VENDOR INTER	09/30/86	Under NRC Review	SCE letter 11/28/83
M52959	B-78	TTEMS 3.1.1 & 3.1.2 - POST MAINTENANCE TEST PROCEDU	11/04/85C	Completed with NRC approval of testing	NRC SER 11/4/85
M53040	B-79	ITEM 3.1.3 - POST MAINTENANCE TESTING - CHANGES TO	08/19/85C	T.S. not required; completed with NRC	NRC SER 8/19/85
				approval	
M53095	B-80	ITEM 4.1 - REACTOR TRIP SYSTEM RELIABILITY - VENDO	07/01/85C	Vendor mods implemented; completed by	NRC SER 7/1/85
				NRC approval	
M53148	B-81	ITEMS 4.2.1 & 4.2.2 -PREVENTATIVE MAINT PROG FOR R	05/30/86	Under NRC Review	SCE letter 5/14/85
M53194	B-82	ITEM 4.3 - AUTOMATIC ACTUATION OF SHUNT TRIP ATTAC	09/24/84C	Provided original design; completed by	NRC SER 11/28/84
				NRC approval	
M54566	B-83	TECH SPECIFICATIONS COVERED BY GENERIC LETTERS 83-	11/02/84C	T.S. being developed in accordance with WC	CAP 10271
M53630	B85	SALEM ATWS 1.2 DATA CAPABILITY	07/31/86	Additional information to be submitted 6/3	0/86
M53713	B-86	SALEM ATWS 2.2 S-R COMPONENTS	01/31/84	Under NRC Review	SCE letter 7/2/85

FACILITY: SAN ONOFRE 1

TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	<u>LICENSEE</u> STATUS	DATE
M53796	B87	SALEM ATWS 3.2.1 & 3.2.2 S-R COMPONENTS	11/04/85C	Completed with NRC approval of information	
M53879	B88	SALEM ATWS 3.2.3 T.S. S-R COMPONENTS	08/19/85C	T.S. not required; completed by NRC	NRC SER 8/19/85
				approval	14KG SEK 67 137 03
M53935	8-89	SALEM ATWS 4.2.3 & 4.2.4 LIFE COMPONENTS	12/31/86	Under NRC Review	SCE letter 4/27/84
M55376	B90	SALEM ATWS 4.3 W AND B&W T.S.	11/28/84C	T.S. being developed to be included with B	
M54106	8-92	SALEM ATWS 4.5.1 DIVERSE TRIP FEATURES	11/04/85C	Deferred to be resolved with B-93	NRC letter 11/04/85
M54023	B-93	SALEM ATWS 4.5.2 & 4.5.3 TEST ALTERNATIVES	05/01/87	Under NRC Review	SCE letter 10/1/84
M06491	C-01	PWR SECONDARY WATER CHEMISTRY MONITORING REQUIREMENT	06/30/82C	Comp. with issuance of license condition	NRC SER 6/30/82
M10150	C-06	PUMP SUPPORT - LAMELLAR TEARING	02/25/82C	Based on NUREG-0577 under generic review b	
M10155	C-07	FUEL HANDLING ACCIDENT INSIDE CONTAINMENT	09/25/78C	2	,
M08082	C-10	CONTROL OF HEAVY LOADS OVER SPENT FUEL POOL (PHASE	11/04/85C	Procedure mods completed 1/15/83	NRC SER 11/4/85
M43664	C-14	AUXILIARY FEEDWATER SEISMIC QUALIFICATION	04/05/82C	To be completed by RTS	6/86
M52268	C-15	CONTROL OF HEAVY LOADS - PHASE II (FOLLOW UP OF MPA	06/28/85C	No SCE action required	NRC SER 6/28/85
M58086	C-16	UTILITY RESPONSES TO STAFF RECOMMENDATIONS CONCERN	12/11/85C	Completed by submittal of information	SCE letter 6/26/85
M13178	DO4	PWR REACTOR VESSEL CAVITY SEAL RING MISSILE POTENT	02/01/84C	200	OGC 100001
M10148	D-10	ASYMMETRIC LOCA LOADS	02/25/82C	GDC 4 revised; SCE to withdraw exemption	SCE letter 9/20/85
				request	3, 10, 10, 10, 10, 10, 10, 10, 10, 10, 10
M10072	D-11	FISSION GAS RELEASE	04/28/81C		
M12293	D15	HIGH ENERGY LINE BREAK & CONSEQUENTIAL SYSTEM FAIL	02/18/81C	Completed with procedural modifications	SCE letter 10/5/79
M43053	D-17	DEFINITION OF OPERABLE	06/11/81C	Completed by issuance of T.S.	6/11/81
M55900	D-19	DIESEL GENERATOR RELIABILITY TECH SPECS (GL 84-15)	01/07/86C	Under NRC Review	SCE letters 2/14/85;
12/19/85					Jon 1600613 2/14/83;
M44057	F-01	I.A.1.1 SHIFT TECHNICAL ADVISOR	01/15/82C	Completed with program implementation	1/1/81

FACILITY: SAN ONOFRE 1

TAC NO.	MPA #	TITLE	LIC ACT	<u>LICENSEE</u> STATUS	DATE
M44128	F-02	I.A.1.3 SHIFT MANNING	02/17/84C	Plans submitted 2/4/82; completed with im	plementation 11/1/82
M44199	F-03	I.A.2.1 UPGRADING OF RO AND SRO TRAINING	10/26/82C	Upgraded plans submitted; completed	NRC SER 10/26/82
				with NRC approval	
M44270	F04	I.C.1.2/3.A EMERGENCY OPERATING PROCEDURES GENERIC	06/07/84C	Completed upgrades	11/27/84
M44340	F-05	I.C.1.2/3.B PROCEDURES GENERATION PACKAGES (NUREG	9/30/86	Completed with submittal of package	SCE letter 4/12/85
M47253	F06	I.C.5 FEEDBACK OF OPERATING EXPERIENCE	01/27/82C	Completed by station procedures issued	5/1/82
M47325	F07	I.C.6 CORRECT PERFORMANCE OF OPERATING ACTIVITIES	02/04/82C	Completed with NRC audit	NRC letter 2/4/82
M51200	F-08	I.D.1.1 DETAILED CONTROL ROOM DESIGN REVIEW PROGRAM	09/31/86	Submittal scheduled for	5/1/87
M51280	F-09	I.D.2 SAFETY PARAMETER DISPLAY SYSTEM	06/01/87	Design Criteria scheduled for 1/9/87;	Plan for final upgrades
					6/1/87
M44407	F-10	II.B.1 RCS HIGH POINT VENTS	08/29/83C	Completed mods in outage ending	11/27/84
M47976	F11	II.B.2 PLANT SHIELDING	04/18/83C	Completed mods in outage ending	11/27/84; NRC SER 4/18/83
M44478	F-12	II.B.3 POST ACCIDENT SAMPLING	11/07//85C	To be completed by RTS	6/86
M44549	F-13	II.B.4 TRAINING FOR MITIGATING CORE DAMAGE	10/26/82C	Completed training 2/10/82; Approved	NRC letter 10/26/82
				by NRC	
M44620	F-14	II.D.1 RV AND SV TESTING	06/30/86	Under NRC review	SCE letters 12/2/82;
					10/17/83; 10/1/85
M44652	F-15	II.E.1.1 AFW SYSTEM EVALUATION	10/22/82C	Completed with NRC approval and T.S.	NRC SER 10/22/82
				issuance	
M44692	F-16	II.E.1.2.1 AFW SYSTEM INITIATION	11/18/82C	Final mods to be completed by RTS	6/86
M44731	F-17	II.E.1.2.2 AFW SYSTEM FLOW INDICATION	11/18/82C	Final mods to be completed by RTS	6/86
M44817	F-18	II.E.4.1 DEDICATED HYDROGEN PENETRATION	11/02/82C	Completed mods in outage ending	6/17/81
M44888	F-19	II.E.4.2 CONTAINMENT ISOLATION DEPENDABILITY	12/30/82C	Completed mods	8/6/81

FACILITY: SAN ONOFRE I

					•
TAC NO.	MPA #	TITLE	LIC ACT COMPLETE	<u>LICENSEE</u> STATUS	DATE
M44959	F-20	II.F.1.1 NOBLE GAS MONITOR	01/29/82C	Completed mods	12/21/82
M45030	F-21	II.F.1.2 IODINE/PARTICULATE SAMPLING	05/13/82C	Completed mods in outage ending	11/27/84
M45101	F-22	II.F.1.3 CONTAINMENT HIGH RANGE MONITOR	02/24/82C	Completed mods in outage ending	11/27/84
M47637	F-23	II.F.1.4 CONTAINMENT PRESSURE INSTRUMENT	04/16/84C	Completed mods in outage ending	11/27/84
M47708	F-24	II.F.1.5 WATER LEVEL INSTRUMENT	04/16/84C	Completed mods in outage ending	11/27/84
M47779	F-25	II.F.1.6 CONTAINMENT HYDROGEN MONITOR	04/16/84C	Completed mods in outage ending	11/27/84
M45171	F-26	II.F.2 INSTRUMENTS FOR DETECTION ON INADEQUATE	01/31/88	ICC report submitted June 20, 1986	
M46906	F-30	II.K.2.13 THERMAL-MECHANICAL REPORT	06/13/84C	WOG analysis submitted; completed with	NRC SER 6/13/84
				NRC approval	
M47819	F-33	II.K.2.17 POTENTIAL FOR VOIDING IN RCS	12/19/83C	WOG analysis submitted; completed with	NRC SER 12/19/83
				NRC approval	
M45249	F-36	II.K.3.1 AUTO PORV ISOLATION	09/13/83C	WOG analysis submitted; completed with	NRC SER 9/13/83
				NRC approval	
M45295	F-37	II.K.3.2 REPORT ON PORV FAILURES	09/13/83C	No action required; completed with NRC SE	R 9/13/83
M45381	F-38	II.K.3.3 REPORTING SV AND RV FAILURES AND CHALLE	03/15/82C	Completed by procedures issued	2/5/81
M45412	F-39	II.K.3.5 AUTO TRIP OF RCPS	02/22/83C	Completed evaluation by SCE letter 10/10/6	85; mods to be scheduled in
				accordance with ILS	
M45461	F-40	II.K.3.9 PID CONTROLLER	01/04/82C	Completed mods in outage ending	6/17/81
M45491	F-41	II.K.3.10 ANTICIPATORY TRIP MODIFICATIONS	01/04/82C	Completed; no mods required	NRC letter 1/4/82
M45521	F-42	II.K.3.12 ANTICIPATORY TRIP ON TURBINE TRIP	01/04/82C	Completed; no mods required	SCE letter 6/13/80
M45667	F47	II.K.3.17 ECCS OUTAGES	08/08/83C	Completed by report submitted	SCE letter 4/20/81
M48433	F-53	II.K.3.25 POWER ON PUMP SEALS	07/07/82C	Completed evaluation by SCE letter 1/11/8:	2; NRC SER 7/7/82
M45864	F-57	II.K.3.30 SB LOCA METHODS	5/30/85C	Completed with submittal of SBLOCA report	WOG letter 6/11/86

FACILITY: SAN ONOFRE 1 (CONTINUATION)

			LIC ACT	LICENSEE	DATE
TAC NO.	MPA #	TITLE	COMPLETE	STATUS	511.
M48203	F58	II.K.3.31 COMPLIANCE WITH 10 CFR 50.46	12/31/86	Completed with submittal of SBLOCA report	WOG letter 6/11/86
M45983	F63	III.A.1.2 TECHNICAL SUPPORT CENTER	07/31/86	Completed mods	10/1/82
M46054	F-64	III.A.1.2 OPERATIONAL SUPPORT CENTER	07/31/86	Completed mods	10/1/82
M46126	F-65	III.A.1.2 EMERGENCY OPERATIONS FACILITY	07/31/86	Completed mods	10/1/82
M46198	F66	III.A.1.2 NUCLEAR DATA LINK	07/30/82C	Not required	
M46270	F-67	III.A.1.2 EMERGENCY PLAN UPGRADE TO MEET RULE	05/09/83C	Completed with NRC audit	NRC letter 5/9/83
M46342	F68	III.A.2.2 METEOROLOGICAL DATA UPGRADE	07/31/86	Under NRC review	SCE letter 12/16/85
M46413	F69	III.D.3.3 IMPLANT RADIATION MONITORING	02/22/82C	Completed with mods and program during out	age ending 6/17/81
M46482	F-70	III.D.3.4 CONTROL ROOM HABITABILITY	02/03/84C	Under NRC Review	SCE letter 3/28/86
M56162	F71	I.D.1.2 DETAILED CONTROL ROOM REVIEW (FOLLOWUP TO	08/01/87	See F-08	
M49685	G01	REACTOR COOLANT PUMP TRIP (D660 - II.K.3.5)	05/01/84C	See F-39	

ACL: 6876F