



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION V

1450 MARIA LANE, SUITE 210  
WALNUT CREEK, CALIFORNIA 94696-5368

AUG 18 1992

Docket Nos. 50-206, 50-361, 50-362

Southern California Edison Company  
Irvine Operations Center  
23 Parker Street  
Irvine, California 92718

Attention: Mr. Harold B. Ray  
Senior Vice President, Nuclear

SUBJECT: NRC INSPECTION OF SAN ONOFRE NUCLEAR GENERATING STATION, REPORT  
NOS. 50-206/92-22, 50-361/92-22, AND 50-362/92-22

This refers to the announced routine inspection conducted by Messrs. Harold D. Chaney and Nader Mamish of this office on July 20-24, 1992, of the activities authorized by NRC license Nos. DPR-13, NPF-10, and NPF-15, and to the findings discussed with Messrs. R. Rosenblum and B. Katz, and other members of your staff identified in the enclosed report, at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements. The violation of concern is your identification of an unmonitored effluent pathway involving the Unit 1 Yard Drainage Sump. The failure to monitor this pathway is considered a violation of 10 CFR Part 50, Appendix A, Criterion 64. However, this violation will not be subject to enforcement action because your efforts in identifying and correcting the violation meet the criteria specified in Section V.G. of the Enforcement Policy.

No deviations were identified during this inspection.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Region/V/ann

DChane

N/A  
NMannish

JReese

REQUEST COPY]	REQUEST COPY]	REQUEST COPY]	SEND TO PDR]
YES / NO ]	YES / NO ]	YES / NO ]	YES / NO ]



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION V**

1450 MARIA LANE  
WALNUT CREEK, CALIFORNIA 94596-5368

**AUG 13 1992**

Docket Nos. 50-206, 50-361, 50-362

Southern California Edison Company  
Irvine Operations Center  
23 Parker Street  
Irvine, California 92718

Attention: Mr. Harold B. Ray  
Senior Vice President, Nuclear

SUBJECT: NRC INSPECTION OF SAN ONOFRE NUCLEAR GENERATING STATION, REPORT  
NOS. 50-206/91-35, 50-361/91-35,  
AND 50-362/91-35

This refers to the announced routine inspection conducted by Messrs. Harold D. Chaney and Nader Mamish of this office on July 20-24, 1992, of the activities authorized by NRC license Nos. DPR-13, NPF-10, and NPF-15, and to the findings discussed with Messrs. R. Rosenblum and B. Katz, and other members of your staff identified in the enclosed report, at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements. The violation of concern is your identification of an unmonitored effluent pathway involving the Unit 1 Yard Drainage Sump. The failure to monitor this pathway is considered a violation of 10 CFR Part 50, Appendix A, Criterion 64. However, this violation will not be subject to enforcement action because your efforts in identifying and correcting the violation meet the criteria specified in Section V.G. of the Enforcement Policy.


No deviations were identified during this inspection.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

IEC6

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,



James H. Reese, Chief  
Reactor Radiological Protection Branch

Enclosure:

Inspection Report Nos. 50-206/92-22, 50-361/92-22, 50-362/92-22

cc w/enclosure:

H. E. Morgan, Vice President and Site Manager  
R. W. Krieger, Station Manager  
State of California

bcc w/enclosures:  
Docket File  
Resident Inspector  
Project Inspector  
G. Cook  
B. Faulkenberry  
J. Martin

bcc w/o enclosure:  
M. Smith  
J. Zollicoffer

Region V/ann

*NLM for*  
DChaney  
8/13/92

*NLM*  
Mamish  
8/13/92

*Reese*  
8/13/92

REQUEST COPY] YES / NO ]	REQUEST COPY] YES / NO ]	REQUEST COPY] YES / NO ]	SEND TO PDR] YES / NO ]
--------------------------	--------------------------	--------------------------	-------------------------