



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V

1450 MARIA LANE
WALNUT CREEK, CALIFORNIA 94596-5368

JAN 26 1993

Docket Nos. 50-206, 50-361, 50-362

Southern California Edison Company
Irvine Operations Center
23 Parker Street
Irvine, California 92718

Attention: Mr. Harold B. Ray, Senior Vice President, Nuclear

SUBJECT: NRC INSPECTION REPORT NOS. 50-206/361/362/92-34

This refers to the routine inspection conducted by Messrs. C. W. Caldwell and D. L. Solorio of this office on December 1, 1992 through January 8, 1993, of activities authorized by NRC License Nos. DPR-13, NPF-10 and NPF-15 and to the discussion of our findings held by the inspectors with Mr. H. E. Morgan and other members of the Southern California Edison staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

Based on the results of this inspection, one of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). This NRC identified violation involved Station Technical personnel performing inservice testing activities that were not in accordance with established radiological control requirements.

In addition, a failure to follow procedure, resulting in improper configuration of a Unit 1 battery charger by Maintenance personnel was reviewed during this inspection. The issue was complicated by the fact that the improper configuration was erroneously accepted by a Quality Control (QC) inspector and by a Maintenance Supervisor. However, since this discrepancy was licensee identified and in view of the actions taken by your staff, a Notice of Violation was not issued since the requirements of Section VII.B of the Enforcement Policy were satisfied. The effectiveness of your corrective action on this matter will be examined during future inspections.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC requirements.

9302180052 930126
PDR ADOCK 05000206
G PDR


JED

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. 96-511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



S. A. Richards, Deputy Director
Division of Reactor Safety
and Projects

Enclosures:

1. Notice of Violation
2. Inspection Report Nos. 50-206/92-34
50-361/92-34
and 50-362/92-34

cc w/enclosures:

H. E. Morgan, Vice President and Site Manager (San Clemente)
R. Krieger, Station Manager (San Clemente)
State of California

bcc w/enclosure:
Project Inspector
Resident Inspector
Docket File
Greg Cook
B. Faulkenberry
J. Martin

bcc w/o enclosure:
M. Smith
J. Zollicoffer
J. Bianchi

RV *See attached concurrence*
CCaldwell 1/26/93
DSolorio *See attached concurrence* 1/26/93
HWong *K* 1/26/93
RHuey *H* 1/24/93

[REQUEST COPY] [REQUEST COPY] [REQUEST COPY] [REQUEST COPY]
[YES / NO] [YES / NO] [YES / NO] [YES / NO]

SR
SRichards
1/26/93

[REQUEST COPY]
[YES / NO]

[SEND TO DCS] [YES / NO]
[SEND TO PDR] [YES / NO]

170007