



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION V

1450 MARIA LANE
WALNUT CREEK, CALIFORNIA 94596-5368

FEB 25 1993

Docket Nos.: 50-206, 50-361 and 50-362
License Nos.: DPR-13, NPF-10 and NPF-15

Southern California Edison Company
Irvine Operations Center
23 Parker Street
Irvine, California 92718

Attention: Mr. Harold B. Ray
Senior Vice President, Nuclear

SUBJECT: NOTICE OF VIOLATION
NRC INSPECTION REPORT NOS. 50-206/93-01, 50-361/93-01 AND 50-362/93-01

This letter refers to the inspection conducted by Messrs. D. Acker and F. Gee between January 11, 1993, and January 29, 1993, of activities authorized by NRC License Nos. DPR-13, NPF-10 and NPF-15, and to the discussion of our findings held with members of your staff on January 29, 1993.

Specific areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, and interviews with personnel.

Based on the results of the inspection, one of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice).

The attached Notice identifies that an emergency diesel generator fuel storage calculation, issued in June 1991, did not correct an error in the previous calculation, and that this error was specifically identified to you in Inspection Report 89-200, dated January 12, 1990. While your preliminary analysis indicates that diesel fuel oil actually stored on site was sufficient during the period that the calculation error existed, this error caused your calculated on-site storage requirement to be short by approximately 2500 gallons per emergency diesel generator.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific action taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

9303120009 930225
PDR ADDCK 05000206
Q PDR

TEO/
11

The response directed by this letter is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96-511. In accordance with 10 CFR 2.790(a), a copy of this letter and enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,


L. F. Miller, Jr., Chief
Reactor Safety Branch

Enclosures:

1. Notice of Violation
2. Inspection Report Nos. 50-206/93-01, 50-361/93-01 and 50-362/93-01

cc w/enclosures (1) and (2):
H. E. Morgan, Vice President and Site Manager
R. W. Krieger, Jr., Station Manager
State of California (Gordon K. Van Vleck)

bcc w/enclosures (1) and (2):

- Docket File
- Resident Inspector
- Project Inspector
- M. Fields, Project Manager
- G. Cook
- B. Faulkenberry
- J. Martin
- H. Wong

bcc w/o enclosures (1) and (2):

- J. Zollicoffer
- M. Smith

Region V/dga

D. Acker
2/14/93

F. Gee
2/19/93

R. Huey
2/17/93

B. Ang
2/25/93

H. Wong
2/25/93

[REQUEST COPY]	[REQUEST COPY]	[REQUEST COPY]	[REQUEST COPY]	[REQUEST COPY]
[YES NO]	[YES NO]	[YES NO]	[YES NO]	[YES NO]

L. Miller
2/25/93

[REQUEST COPY]
[YES NO]

[SEND TO PDR]
[YES NO]

110030