

ENCLOSURE 1

NOTICE OF VIOLATION

Southern California Edison Company
San Onofre Unit 2 and 3

Docket No. 50-361, 50-362
License No. NPF-21, NPF-15

During an NRC inspection conducted on July 17 through August 26, 1993, violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedures for NRC Enforcement Actions," the violations are listed below:

10 CFR 50.9, **Completeness and accuracy of information**, requires, in part, that information required by statute or by Commission regulations, orders, or license conditions to be maintained by the licensee shall be complete and accurate in all material respects.

Contrary to the above, the licensee determined that records required to be maintained by Commission regulations or license conditions were not complete and accurate in all material respects. Specifically, during the period of July 17 through August 26, 1992, three records made by one individual were identified as being incomplete or inaccurate. These errors were material in that they evidenced that checks had been made when they had not.

bcc w/enclosure:

Docket File
G. Cook
B. Faulkenberry
Resident Inspector(5)
Project Inspector

bcc w/o enclosure:

LFMB
M. Smith

CCaldwell ^{BS}
9/1/93
per telecon

Bolton ^{BS}
9/1/93

^K
HWong
9/1/93

^H
RHuey
9/3/93

^{CW}
CVanDenburgh
9/1/93

REQUEST COPY YES / <u>NO</u>	REQUEST COPY YES / <u>NO</u>	REQUEST COPY <u>YES</u> / NO	REQUEST COPY <u>YES</u> / NO	REQUEST COPY <u>YES</u> / NO
---------------------------------	---------------------------------	---------------------------------	---------------------------------	---------------------------------

SRichards
1/93

KPerkins ^{BS}
9/5/93

^{BS}
BFaulkenberry
10/14/93

REQUEST COPY YES / NO	REQUEST COPY YES / NO	REQUEST COPY YES / <u>NO</u>
--------------------------	--------------------------	---------------------------------

SEND TO DCS	<u>YES</u> / NO
SEND TO PDR	<u>YES</u> / NO