

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C A S O S 1 | 2 0 0 - 0 0 0 0 0 0 - 0 0 | 3 4 1 1 1 1 | 4 | 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
0 1 | REPORT SOURCE | L | 6 0 5 0 0 0 2 0 6 | 7 0 6 0 4 7 9 | 8 0 6 1 8 7 9 | 9
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During a maintenance outage, while conducting eddy current testing,
0 3 | eighteen defective tubes were discovered in steam generator A. All tube
0 4 | defects were located in the area of the tubesheet. One tube was leaking
0 5 | at about 80 gallons per day (6.9.2.a(9)).
0 6 |
0 7 |
0 8 |

0 9 | SYSTEM CODE | C C | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | D | 13 | COMPONENT CODE | H T E X C H | 14 | COMP. SUBCODE | F | 15 | VALVE SUBCODE | Z | 16
7 8 9 10 11 12 13 18 19 20
17 | LER/RO REPORT NUMBER | EVENT YEAR | 7 9 | 21 22 | SEQUENTIAL REPORT NO. | 0 0 8 | 24 26 | OCCURRENCE CODE | 0 1 | 28 29 | REPORT TYPE | T | 30 31 | REVISION NO. | 0 | 32
ACTION TAKEN | 8 | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | A | 20 | SHUTDOWN METHOD | A | 21 | HOURS | 0 3 6 0 | 22 | ATTACHMENT SUBMITTED | V | 23 | NPRD-4 FORM SUB. | Y | 24 | PRIME COMP. SUPPLIER | N | 25 | COMPONENT MANUFACTURER | W T 2 0 | 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Tube failures are due to corrosion in the area of the tubesheet. All
1 1 | tubes with greater than 50% wall thinning were plugged. Steam generator
1 2 | is Westinghouse Model 27. Phosphate chemistry is in use.
1 3 |
1 4 |

1 5 | FACILITY STATUS | G | 28 | % POWER | 0 0 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Eddy Current Testing | 32
7 8 9 10 12 13 44 45 46 80

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | Z | 34 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36
7 8 9 10 11 44 45 80

1 7 | PERSONNEL EXPOSURES NUMBER | 0 0 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39
7 8 9 11 12 13 80

1 8 | PERSONNEL INJURIES NUMBER | 0 0 0 | 40 | DESCRIPTION | NA | 41
7 8 9 11 12 80

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43
7 8 9 10 80

2 0 | PUBLICITY ISSUED | Y | 44 | DESCRIPTION | Press Release | 45
7 8 9 10 80

NRC USE ONLY
68 69 80

NAME OF PREPARER J. M. Curran

PHONE: (714) 492-7700




FIGURE 1

SCE-A
series 27




FIGURE 2

SCC-C

series 27