## Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92674-0128

September 21, 1990

R. W. KRIEGER STATION MANAGER

> U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Docket No. 50-206 Voluntary Report Licensee Event Report No. 89-010 San Onofre Nuclear Generating Station, Unit 1

Enclosed is a voluntary Licensee Event Report (LER) for an occurrence involving core power distribution monitoring. This voluntary report is provided consistent with a commitment made in our March 17, 1989 submittal to the NRC regarding technical issues impacting the San Onofre Unit 1 restart from the Cycle X refueling outage. The March 17 submittal provided a discussion of this subject with an assessment which concluded that this condition was not safety significant. This voluntary report provides a more detailed discussion of this issue which results from our continued follow-up investigation and review process. This process resulted in circumstances which prolonged the preparation and submittal of this report. SCE endeavors to avoid such circumstances, and will continue to do so in the future.

This occurrence had no effect on the health and safety of either plant personnel or the public.

If you require any additional information, please so advise.

HACErelv

Enclosure: LER No. 89-010

cc: C. W. Caldwell (USNRC Senior Resident Inspector, Units 1, 2 and 3)
J. B. Martin (Regional Administrator, USNRC Region V)
Institute of Nuclear Power Operations (INPO)

9010110042 900921 PDR ADOCK 05000206 PNU 6CL.J

TELEPHONE (714) 368-6255