

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8102030555 DOC. DATE: 81/01/21 NOTARIZED: NO DOCKET #  
 FACIL: 50-206 San Onofre Nuclear Station, Unit 1, Southern California 05000206  
 AUTH. NAME: CURRAN, J.M. AUTHOR AFFILIATION: Southern California Edison Co.  
 RECIP. NAME: RECIPIENT AFFILIATION: Region 5, San Francisco, Office of the Director

SUBJECT: LER 81-039/03L-1: on 801211, worn thrust bearings found on all four turbochargers on emergency diesel generator 1. Exact cause of thrust bearing wear being investigated. Emergency diesel generator 2 available until bearings repaired.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+1  
 TITLE: Incident Reports

NOTES: 1 cy each: SEP Section Leader & J Hanchett (Region V) 05000206

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	CRUTCHFIELD 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	A/D TECHNOLOG13	1	1
	ACC EVAL BR 14	1	1	AEOD	3	3
	ASLBP/J.HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18	1	1	DIR, DIV OF LIC	1	1
	DIR, ENGINEER120	1	1	DIR, HUM FAC S21	1	1
	DIR, SYS INTEG22	1	1	EFF TR SYS BR23	1	1
	EQUIP QUAL BR25	1	1	GEOSCIENCES 26	1	1
	I&C SYS BR 29	1	1	I&E 05	2	2
	JORDAN, E./IE	1	1	LIC GUID BR 30	1	1
	MATL ENG BR 32	1	1	MECH ENG BR 33	1	1
	MPA	3	3	NRC PDR 02	1	1
	OP EX EVAL BR34	3	3	OR ASSESS BR 35	1	1
	POWER SYS BR 36	1	1	RAD ASSESS BR39	1	1
	REACT SYS BR 40	1	1	<del>REG FILE</del> 01	1	1
	REL & RISK A 41	1	1	SFTY PROG EVA42	1	1
	STRUCT ENG BR44	1	1	SYS INTERAC B45	1	1
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	1
	NSIC 05	1	1	TERA: DOUG MAY	1	1

FEB 05 1981

V

TOTAL NUMBER OF COPIES REQUIRED: LTR 71 ENCL 71

