

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED: Rapid City Regional Hospital 353 Fairmont Boulevard Rapid City, South Dakota 57701 Location: 1420 N. 10th St., Spearfish, SD and 2929 5th St., Rapid City, SD REPORT NO: 030-03231/2013-002</p>	<p>2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission - Region IV 1600 East Lamar Boulevard Arlington, Texas 76011-4511</p>	
<p>3. DOCKET NUMBER 030-03231</p>	<p>4. LICENSE NUMBER 40-00238-01</p>	<p>5. DATES OF INSPECTION July 29 through August 01, 2013</p>

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.




10 CFR 35.610(e) requires the licensee to ensure that operators, authorized medical physicists, and authorized users participate in drills of the emergency procedures, initially and at least annually.

Contrary to the above, the licensee failed to ensure that operators, authorized medical physicists, and authorized users participated in annual drills of the emergency procedures. Specifically, from 2009 to 2012, an annual drill of the emergency procedures was not conducted.

The licensee agreed to conduct a drill of the emergency procedures which will involve participation of the operators, authorized medical physicists, and authorized users within 30 days of this inspection and every year thereafter. The licensee will retain a record of these drills.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Paul Clemments, VP of Prof. Serv.		08/01/2013
NRC INSPECTOR	R. Rick Muñoz		08/01/2013
BRANCH CHIEF	G. Michael Vasquez		10/8/2013