Comanche Peak Nuclear Power Plant, Units 3 & 4 COL Application Part 2, FSAR




Figure 2.5.2-226 Deaggregation of 10⁻⁴ Rock Hazard for 1 and 2.5 Hz