

# REGULATORY GUIDE

OFFICE OF STANDARDS DEVELOPMENT

## REGULATORY GUIDE 3.27

## NONDESTRUCTIVE EXAMINATION OF WELDS IN THE LINERS OF CONCRETE BARRIERS IN FUEL REPROCESSING PLANTS

### A. INTRODUCTION

Section 50.34, "Contents of Applications; Technical Information," of 10 CFR Part 50, "Licensing of Production and Utilization Facilities," requires, among other things, that each application for a construction permit or operating license for a fuel reprocessing plant include a discussion of how the applicable requirements of Appendix B, "Quality Assurance Criteria for Nuclear Power Plants and Fuel Reprocessing Plants," to 10 CFR Part 50 will be satisfied. As used in Appendix B, "quality assurance" comprises all those planned and systematic actions necessary to provide adequate confidence that safety-related structures, systems, and components will perform satisfactorily in service. Appendix B requires, in part, that measures be established to ensure that special processes, including welding, heat treating, and nondestructive testing, are controlled and accomplished by qualified personnel using qualified procedures.

The leaktight integrity of metal liners of concrete confinement barriers is an important consideration in safety evaluations. This guide describes procedures acceptable to the NRC staff for meeting the above requirements with regard to the nondestructive examination of welds in the metal liners and penetrations of confinement barriers of concrete construction. This guide applies to metal liners of process cells, fuel storage pools, waste storage tank vaults, and other concrete confinement barriers in fuel reprocessing plants.

### B. DISCUSSION

Metal liners of confinement systems in fuel reprocessing plants keep radiochemicals from contaminating the environs. Because their leaktight integrity is an important consideration in the safety evaluation of fuel reprocessing plants, through-thickness cracks in these

liners are unacceptable. Surface cracks and other weld defects that can hold up radioactive solutions or particulates may complicate decontamination of the liners for decommissioning or when direct repair, maintenance, or inspection of the liner or of other components within the liner must be made. They can also cause leakage of the liner by initiating accelerated crevice corrosion by either the operation or decontamination environment. These surface cracks and weld defects, therefore, should be avoided.

The leaktight integrity of confinement barrier liners should be confirmed by examination. Many acceptable nondestructive testing methods and procedures are available and have been used for the examination of liner welds. These practices have differed significantly because there has not been sufficient guidance toward standardization. This guide standardizes procedures acceptable to the NRC staff for the nondestructive examination of liner welds. These procedures, which draw on those used for nuclear power plants, will provide a uniform quality level consistent with the safety function of confinement barrier liners in fuel reprocessing plants.

### C. REGULATOR POSITION

Welds in the metal liners of concrete confinement barriers in fuel reprocessing plants should be nondestructively examined using the following methods:

#### 1. Nondestructive Examination Methods for Liner Seam Welds

a. For each welder and welding position (flat, vertical, horizontal, and overhead), the first 10 feet of weld and a minimum of one spot (not less than 12 inches in length) in each additional 50-foot increment of weld (weld test unit) or fraction thereof should be examined radiographically.

#### USNRC REGULATORY GUIDES

Regulatory Guides are issued to describe and make available to the public methods acceptable to the NRC staff of implementing specific parts of the Commission's regulations, to delineate techniques used by the staff in evaluating specific problems or postulated accidents, or to provide guidance to applicants. Regulatory Guides are not substitutes for regulations, and compliance with them is not required. Methods and solutions different from those set out in the guides will be acceptable if they provide a basis for the findings requisite to the issuance or continuance of a permit or license by the Commission.

Comments and suggestions for improvements in these guides are encouraged at all times, and guides will be revised, as appropriate, to accommodate comments and to reflect new information or experience. However, comments on this guide, if received within about two months after its issuance, will be particularly useful in evaluating the need for an early revision.

Comments should be sent to the Secretary of the Commission, U.S. Nuclear Regulatory Commission, Washington, D.C. 20555, Attention: Docketing and Service Section.

The guides are issued in the following ten broad divisions:

- |                                   |                        |
|-----------------------------------|------------------------|
| 1. Power Reactors                 | 6. Products            |
| 2. Research and Test Reactors     | 7. Transportation      |
| 3. Fuels and Materials Facilities | 8. Occupational Health |
| 4. Environmental and Siting       | 9. Antitrust Review    |
| 5. Materials and Plant Protection | 10. General            |

Copies of published guides may be obtained by written request indicating the divisions desired to the U.S. Nuclear Regulatory Commission, Washington, D.C. 20555, Attention: Director, Office of Standards Development.

b. Where radiographic examination of liner seam welds is not feasible or where the weld is located in an area that will not be accessible after the construction of the confinement barrier, the entire length of weld should be examined by the ultrasonic method or the magnetic-particle method for magnetic welds or by the ultrasonic method or the liquid-penetrant method for nonmagnetic welds.

c. All liner seam welds should be tested for leaktightness by the vacuum box method, by the halogen diode method, or by the helium mass spectrometer method (or by other methods of equivalent sensitivity).

d. Where leak-chase-system channels are installed over liner welds, channel-to-liner-plate welds should be tested for leaktightness by pressurizing the channels to a minimum pressure of 25 psi gauge. If any indicated loss of channel test pressure occurs within 2 hours, as evidenced by a test gauge that meets the requirements of NB-6400 of Section III of the American Society of Mechanical Engineers Boiler and Pressure Vessel Code\* (ASME Code), the channel-to-liner welds should be leak tested by one of the methods specified in regulatory position C.1.c above.

## 2. Nondestructive Examination Methods for Penetration, Airlock, and Access Opening Welds

a. All welds in penetrations, airlocks, and access openings that are not backed by concrete, such as welds between penetrations and flued fittings and between flued fittings and pipelines, should be fully examined in accordance with the examination methods of NE-5200 of Section III of the ASME Code. Procedures and techniques that should be used for these examination methods are given in regulatory position C.3 of this guide.

b. All welds in the vicinity of penetrations, airlocks, and access openings that are backed by concrete, such as welds between penetration and reinforcing plate,\*\* penetration and liner, reinforcing plate and liner, liner insert and liner, reinforcing plate and frames for airlocks and access openings, and liners and frames for airlocks and access openings, should be fully examined (1) in accordance with regulatory position C.2.a above or (2) by the magnetic-particle method for magnetic welds or the liquid-penetrant method for nonmagnetic welds.

c. All welds in bellows-type expansion joints provided in penetration assemblies should be tested by the magnetic-particle method for magnetic welds or by the liquid-penetrant method for nonmagnetic welds.

\*American Society of Mechanical Engineers Boiler and Pressure Vessel Code, 1974 Edition. All references to the ASME Code are to the 1974 edition. Copies may be obtained from the American Society of Mechanical Engineers, United Engineering Center, 345 East 47th Street, New York, N.Y. 10017.

\*\*Thickened liner insert that provides local reinforcement.

## 3. Nondestructive Examination Procedures and Techniques

a. Radiographic examination should be performed in accordance with the techniques and requirements of Articles 1 and 2 of Section V, "Nondestructive Examination," of the ASME Code.

b. Magnetic-particle examination should be performed in accordance with Articles 1 and 7 of Section V of the ASME Code.

c. Ultrasonic examination should be performed in accordance with Articles 1 and 5 of Section V of the ASME Code.

d. Liquid-penetrant examination should be performed in accordance with Articles 1 and 6 of Section V of the ASME Code.

e. Leak testing by the vacuum box method should be performed in accordance with Article 1 of Section V of the ASME Code and Appendix A to this guide. Leak testing by the halogen diode method should be performed in accordance with Articles 1 and 10 of Section V of the ASME Code. Leak testing by the helium mass spectrometer method should be performed in accordance with Articles 1 and 10 of Section V of the ASME Code.

## 4. Qualification of Nondestructive Examination Personnel

Nondestructive examination should be performed by personnel designated by the licensee or his agent and qualified in accordance with the provisions of Article 1, and other applicable articles for the particular test method used, of Section V of the ASME Code.

## 5. Selection of Spots for Radiographic Examination

The spots of liner seam welds to be radiographically examined should be randomly selected, but no two spots in adjacent weld test units should be closer than 10 feet. Locations of examined spots should be recorded.

## 6. Time of Examination

All examinations should be performed as soon as practicable after completion of the lineal increment of weld to be examined. If postweld heat treatment is required, examinations should be performed as soon as practicable after the heat treatment.

## 7. Postexamination Cleaning

Following each procedure in which examination materials remain on the surface, the surface should be cleaned in accordance with the requirements for the finished liner.

## 8. Acceptance Standards

a. All welds examined by radiography are acceptable if they meet the acceptance standards of NE-5320 of Section III of the ASME Code. Where a spot in the liner seam weld is judged acceptable, the entire weld test unit represented by this spot radiograph is considered acceptable.

b. Welds examined by the ultrasonic method are acceptable if they meet the acceptance standards of NE-5330 of Section III of the ASME Code.

c. Welds examined by the magnetic-particle method are acceptable if they meet the acceptance standards of NE-5340 of the ASME Code, except that the following relevant indications should be considered unacceptable:

(1) Rounded defects with dimensions greater than 3/16 inch,

(2) Four or more rounded defects in a line separated by 1/16 inch or less (edge to edge), and

(3) Ten or more rounded defects in any six square inches of surface where this area is taken in the most unfavorable location relative to the defects being evaluated.

d. Welds examined by the liquid-penetrant method are acceptable if they meet the acceptance standards of NE-5350 of the ASME Code, except that the following relevant indications should be considered unacceptable:

(1) Rounded defects with dimensions greater than 3/16 inch,

(2) Ten or more rounded defects in any six square inches of surface where this area is taken in the most unfavorable location relative to the defects being evaluated.

e. Welds showing through-thickness indications by leak testing should be considered unacceptable. Leak-tested welds are acceptable if they meet the acceptance standards of Article 10 of Section V of the ASME Code for the particular leak test method used.

## 9. Repair and Reexamination

a. When a radiographed spot fails to meet the specified acceptance standards, two additional spots should be radiographically examined in the same weld test unit at locations at least one foot removed (on each side) from the original spot. The locations of these additional spots should be determined by the examiner using the same procedure as that followed in the selection of the original spot for examination, and the examination

results should determine the proper corrective actions as follows:

(1) If the two additional spots examined meet the specified acceptance standards, the entire weld unit represented by the three spot radiographs is considered acceptable. However, the defective welding disclosed by the first of the three radiographs should be repaired by welding.

(2) If either of the two additional spots examined fails to meet the specified acceptance standards, the entire weld test unit should be considered unacceptable. The entire weld should be removed and the joint should be rewelded or, optionally, the entire weld unit may be completely radiographed and only defective welding need be repaired.

(3) Repair welding should be performed using qualified welders, welding machine operators, and procedures equivalent to those used in the original weld or in accordance with Section IX, "Welding and Brazing Qualifications," of the ASME Code. Each weld repaired area in each weld test unit should be spot radiographed at least at one selected location and should meet the criteria specified in regulatory positions C.8.a and C.9.a.

b. All other welds examined by any of the applicable methods of regulatory positions C.1 and C.2 above that fail to meet the specified acceptance standards (regulatory position C.8 above) should be repaired and reexamined in accordance with NE-4400 of Section III of the ASME Code and regulatory position C.4 above.

## 10. Records

Records of radiographs and other nondestructive examinations including those for repaired defective welds should be retained by the licensee in compliance with the provisions of Criterion XVII, "Quality Assurance Records," of Appendix B to 10 CFR Part 50.

## D. IMPLEMENTATION

The purpose of this section is to provide information to applicants and licensees regarding the NRC staff's plans for using this regulatory guide.

Except in those cases in which the applicant proposes an acceptable alternative method for complying with specified portions of the Commission's regulations, the method described herein will be used in the evaluation of submittals for construction permit applications docketed after October 6, 1975.

If an applicant wishes to use this regulatory guide in developing submittals for applications docketed on or before October 6, 1975, the pertinent portions of the application will be evaluated on the basis of this guide.

## APPENDIX A

### VACUUM BOX EXAMINATION OF LINER SEAM WELDS

1. **Scope:** This appendix gives the procedure and requirements for examination of welds by the vacuum box method. Much of the information presented is adapted for this test method from different parts of Section V of the ASME Code.
2. **Application:** The vacuum box examination method allows through-thickness indications such as leaks, pores, and the lack of fusion in welds to be detected. The method does not allow for quantitative determinations, but the presence of leaks and their positions can be determined. A bubble-forming solution is applied to the weld, and a vacuum box with a viewing window is placed over the area to be tested. The box is evacuated, and through-thickness leaks are detected by the formation of bubbles on the surface.
3. **Written Procedure:** The vacuum box test examination should be performed to detailed written procedures in accordance with Article 1 of Section V of the ASME Code and with the applicable requirements of this appendix.
4. **Personnel Qualification:** Personnel performing leak testing by the vacuum box method should be qualified in accordance with the requirements of Article 1 of Section V of the ASME Code.
5. **Procedure:** The following procedure should be used for weld examination by the vacuum box method:
  - a. **Surface Preparation.** (Adapted from Article 6, Section V, ASME Code). Satisfactory results are obtained when the surface is in the as-welded condition. The surface to be examined should be free of any dirt, grease, paint, scale, welding flux, weld spatter, slag or other material that could otherwise interfere with the examination or the interpretation of the test results. Cleaning may be accomplished by wire brushing with a stainless steel brush or by the use of cleaning agents such as detergents, organic solvents, descaling solutions, and paint removers. Cleaning solvents should meet the requirements of T-630(b) of Article 6 of Section V of the ASME Code. Drying, after cleaning, of the surfaces to be examined should be accomplished by normal evaporation or with forced hot air, as appropriate. A minimum period of time should be established and included in the procedure to ensure that the cleaning

solution has evaporated prior to application of the bubble-forming solution.

b. **Bubble Solution.** The bubble-forming solution should produce a film that does not break away from the area to be tested, and the bubble formed should not break rapidly due to air drying or low surface tension. The number of bubbles contained in the solution should be minimized to reduce the problem of discriminating between existing bubbles and those caused by the test. Ordinary household soap or detergents should not be permitted as substitutes for bubble-testing solutions in which, in principle, a bubble will form when there is leakage present. (The above description is taken from Article 6, Section V, ASME Code.) The test solution should be checked every hour with a suitable test leak to verify the bubble formation property of the solution used.

c. **Application of Solution.** The bubble-forming solution is applied to the low pressure side of the surface to be examined. The entire test area should be evenly coated by flowing the solution over it. The temperature of the surface to be examined should be in the range 40° to 100° F. The solution should be applied immediately before the test but not more than 1 minute before testing.

d. **Vacuum Test.** A vacuum box containing a viewing window is placed over the area to be tested and evacuated to produce at least 5 psi differential with the atmospheric pressure. The 5 psi differential in pressure should be verified by the use of a calibrated gauge and maintained for a minimum of 20 seconds. Leaks in welds, if present, are detected by formation of bubbles. An overlap of 2 inches should be used for each additional examination along the seam weld.

e. **Visual Examination.** (T-1032.3 of Article 10, Section V, ASME Code). When performing the visual examination, access to the area to be viewed should permit placing the eye within at least 24 in. of the surface to be examined, at an angle of no less than 30 deg with the surface to be examined. Mirrors may be used to improve the angle of vision, and aids such as magnifying lenses may be used to assist examinations. Natural or artificial lighting may be used to illuminate the area to be examined. The lighting in the area to be examined should be a minimum of 350 lux (32.5 footcandles).

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555  
OFFICIAL BUSINESS  
PENALTY FOR PRIVATE USE \$100

POSTAGE AND FEES PAID  
U.S. NUCLEAR REGULATORY  
COMMISSION

