ES-401

Record of Rejected K/As

Form ES-401-4

Tier / Group	Randomly Selected K/A	Reason for Rejection
2/1	209001.G2.2.3	There are no significant unit differences associated with the Core Spray systems. Randomly selected G2.4.21 from the previously unused Generic K/As.
1/1	G.2.1.38	Repicked Generic K/A to comply with ES 401, D.1.b of NUREG 1022 since G.2.1.38 was not included on the 'select' list.
1/1	295016 AK 3.02	Repicked AK3.01, 'Reactor Scram' in lieu of 'Turbine Trip' since turbine trip had no references in licensee's control room abandonment procedure.
1/1	295025 EK3.02	Question written for EK3.02 HIGH RX PRESSURE and recirc pump trip better matched K/A EA1.07 HIGH RX PRESSURE and ATWS.
2/2	201003 K5.04	Repicked K5.06, How control rod with varies with moderator temperature and voids in lieu of 'rod sequence patterns' since could not create a question from original pick.
1/1 SRO	295001 AA2.06	Could not find any references relating loss of recirc flow and boiler instrumentation at SRO level. Repicked G 2.1.20, Ability to interpret and execute procedure steps.
1/1 SRO	295016 G2.4.23	Repicked Generic K/A to comply with ES 401, D.1.b of NUREG 1022 since G 2.4.23 was not included on 'select' list. Repicked Generic K/A G2.2.40.
1/1 SRO	295024 EA2.05	Suppression chamber air space temperature is a plant- specific K/A not applicable to BWR 4 design. Repicked K/A 295024 from EA2.05 to EA2.06, Suppression Pool temperature.
2/1	211000.K1.10	There is no interface between the SLC and HPCI systems at Dresden. Randomly selected K1.03 as a replacement.
1/1	295038 G2.2.2	Repicked Generic K/A to comply with ES 401, D.1.b of NUREG 1022 since G.2.2.2 was not included on the 'select' list. Repicked G.2.4.30.
1 / 2 SRO	295007/295025 High Rx Press	High Reactor Pressure was previously selected for Q80 SRO. Do not want to sample same attribute again for Q83! Repicked 295008, High Reactor Water level; (same K/A: AA2.03, RWCU Blowdown flow.)
1 / 2 SRO	295022 G2.2.21	Repicked Generic K/A to comply with ES 401, D.1.b of NUREG 1022 since G 2.2.21 was not included on 'select' list. Repicked Generic K/A G2.1.23.
2 / 2 RO	272000 G2.4.13	Repicked Generic K/A to comply with ES401, D.1.b of NUREG 1022 Since G.2.4.13 was not included on 'select' list. Repicked Generic K/A 2.2.37.
2 / 1 SRO	203000 G2.3.11	Repicked Generic K/A to comply with ES 401, D.1.b of NUREG 1022 since G2.3.11 was not on the 'select' list. Repicked Generic K/A G2.1.20.
2 / 1 SRO	212000 G2.2.42	Entry level TS recognition is not SRO-only. Randomly selected G2.2.12.

2 / 2 SRO	245000 G2.1.37	Repicked Generic K/A to comply with ES 401, D.1.b of NUREG 1022 since G2.1.37 was not on the 'select' list. Repicked Generic K/A G2.1.31.
Tier / Group	Randomly Selected K/A	Reason for Rejection
3 RO	2.2.15	Testing the ability to determine plant configuration using drawings, etc. is better suited for a JPM. Repicked Generic K/A G2.2.7.
2 / 1 RO	300000 K4.01	Repicked to K4.02 since there are no automatic transfers of control for IA system.
2 / 1 RO	262002 UPS (AC/DC) K1.09	Repicked to K3.06 due to inability to write a discriminating question on the cause/effects of UPS on DW Vent control.
1 / 1 RO	295001 AA1.03	Plant Specific K/A. Can not write question to this K/A. Repicked AA1.07, Nuclear Boiler Instrumentation.
2 / 2 RO	219000 K6.09	Could not identify a question to fit this K/A. Repicked K6.01, Loss of AC power.
2 / 2 RO	259001 K1.13	Repicked K/A since question better suited to K/A 256000 K1.06.
1 / 2 RO	295015 G2.1.36	K/A related to core alterations is not compatible with Incomplete SCRAM event. Randomly selected G2.4.35
2 / 1 RO	239002 A2.06	Changed K/A to match a licensee bank question. Previous question was rated unsat by licensee validators. Q40 replaced.
1/1R0	295021 G2.1.19	Repicked K/A since licensee does not require students to memorize computer screens. Q9 replaced.