

Tier / Group	Randomly Selected K/A	Reason for Rejection
1/1 (RO)	700000 K3.01	KA selection resulted in oversampling error. Selection of the other K3 item also resulted in error. Randomly selected K2.02.
1/1 (RO)	295027 K2.01	Not Applicable to Fermi – Not Mark III Containment Selected 600000 K2.01 – Not previously selected
1/1 (RO)	295030 A1.01	Possible oversampling (NPSH topic) with 295026 K1.01. Randomly selected 295030 A1.02.
2/2 (RO)	290002 K6.05	No operationally valid question could be written. Randomly selected 290002 K6.03.
1/1 (RO)	295024 A2.03	No operationally valid question could be written. Randomly selected 295024 A2.01.
3 (RO)	Conduct of Operations 2.1.14	No operationally valid question could be written. Randomly selected 2.1.45.
	Replaced JPM (form 301-2, h.)	Original JPM (Switch Off Gas Recombiner Chains) did not run as expected. Simulator Group is investigating. Replaced with JPM (Perform SGTS Filter & Isolation Damper Op Test) in same Safety Function.
	Replaced JPM (form 301-2, k.)	Original JPM (Startup Fuel Pool Ventilation Exhaust Radiation Monitor) could not be performed as expected. Replaced with JPM (Place RHRSW Radiation Monitor in Service) in same Safety Function.
